

(To be submitted at the time of Registration of Ongoing Project and for withdrawal of Money from Designated Account)

NO.....

Date: 30-Dec-23

**Arcop
Associates
Private
Limited**
**Architecture
Planning
Urban Design
Interiors**

Subject: Certificate of Percentage of Completion of Construction Work of 5 No. of Building(s)/Block(s) of the Godrej Nest - Phase 1 (UPRERA Registration Number - UPRERAPRJ13521) situated on the Kharsa No/ Plot no SC-02, H&I, Sector-150, Noida Demarcated by its boundaries (latitude and longitude of the end points) 28 25 12. 36N to the North 28 25 11. 10N to the South 77 29 33. 44E to the East 77 29 43. 39E to the West of village - Gautam Buddha Nagar Tehsil - Gautam Buddha Nagar Competent/ Development authority District- Gautam Buddha Nagar, Noida PIN 201301 admeasuring 11550 sq.mts. area being developed by Brickrise Developers Pvt Ltd.

We M/s ARCOP Associates Pvt. Ltd have undertaken assignment as Architect/Licensed Surveyor of certifying Percentage of Completion

1. Following technical professionals are appointed by owner / Promotor :-
(i) M/s/Shri/Smt ARCOP Associates Pvt Ltd. as L.S. / Architect ;
(ii) M/s/Shri/Smt TPC Technical Projects Consultants Pvt. Ltd. as Structural Consultant
(iii) M/s/Shri/Smt CP VIDYA Associates as MEP Consultant
(iv) M/s/Shri/Smt Cushman & Wakefield India Pvt. Ltd. as Site Supervisor

Based on Site Inspection, with respect to each of the Buildings /Blocks/Towers of the aforesaid Real Estate Project, I certify that as on the date of this certificate, the Percentage of Work done for each of the Buildings /Blocks/Towers of the Real Estate Project as registered vide number UPRERAPRJ13521 under UPRERA is as per table A herein below. The percentage of the work executed with respect to each of the activity of the entire phase is detailed in the Table B.

Table A

Tower A1		
Sr. No.	Task/Activity	Percentage Work Done
1	Excavation	100%
2	Raft/Pilinth	100%
3	1 number of Basement(s)	100%
4	0 number of Podiums	0%
5	Stilt Floor	100%
6	17 number of Slabs of Super Structure	100%
7	Internal walls, Internal Plaster, Flooring within Flats/Premises, Doors and Windows in each of the	74%
8	Sanitary Fittings within the Flat/Premises, Electrical Fittings within the Flat/premises	0%
9	Staircases, Lift Wells and Lobbies at each Floor level connecting Staircases and Lifts, Overhead and	75%
10	The external plumbing and external plaster, Elevation, completion of terraces with waterproofing of the	75%
11	Installation of lifts, water pumps, Fire Fighting Fittings and Equipments as per CFO NOC, Electrical fittings to	0%

Tower A2		
Sr. No.	Task/Activity	Percentage Work Done
1	Excavation	100%
2	Raft/Pilinth	100%
3	1 number of Basement(s)	100%
4	0 number of Podiums	0%
5	Stilt Floor	100%
6	17 number of Slabs of Super Structure	100%
7	Internal walls, Internal Plaster, Flooring within Flats/Premises, Doors and Windows in each of the	75%
8	Sanitary Fittings within the Flat/Premises, Electrical Fittings within the Flat/premises	0%
9	Staircases, Lift Wells and Lobbies at each Floor level connecting Staircases and Lifts, Overhead and	77%
10	The external plumbing and external plaster, Elevation, completion of terraces with waterproofing of the	75%
11	Installation of lifts, water pumps, Fire Fighting Fittings and Equipments as per CFO NOC, Electrical fittings to	0%

Tower C1		
Sr. No.	Task/Activity	Percentage Work Done
1	Excavation	100%
2	Raft/Pilinth	100%
3	1 number of Basement(s)	100%
4	0 number of Podiums	0%
5	Stilt Floor	100%
6	20 number of Slabs of Super Structure	100%
7	Internal walls, Internal Plaster, Flooring within Flats/Premises, Doors and Windows in each of the	79%
8	Sanitary Fittings within the Flat/Premises, Electrical Fittings within the Flat/premises	0%
9	Staircases, Lift Wells and Lobbies at each Floor level connecting Staircases and Lifts, Overhead and	86%
10	The external plumbing and external plaster, Elevation, completion of terraces with waterproofing of the	75%
11	Installation of lifts, water pumps, Fire Fighting Fittings and Equipments as per CFO NOC, Electrical fittings to	0%

Tower B3		
Sr. No.	Task/Activity	Percentage Work Done
1	Excavation	100%
2	Raft/Pilinth	100%
3	1 number of Basement(s)	100%
4	0 number of Podiums	0%
5	Stilt Floor	100%
6	20 number of Slabs of Super Structure	100%
7	Internal walls, Internal Plaster, Flooring within Flats/Premises, Doors and Windows in each of the	78%
8	Sanitary Fittings within the Flat/Premises, Electrical Fittings within the Flat/premises	0%
9	Staircases, Lift Wells and Lobbies at each Floor level connecting Staircases and Lifts, Overhead and	91%
10	The external plumbing and external plaster, Elevation, completion of terraces with waterproofing of the	80%
11	Installation of lifts, water pumps, Fire Fighting Fittings and Equipments as per CFO NOC, Electrical fittings to	0%

Tower D1		
Sr. No.	Task/Activity	Percentage Work Done
1	Excavation	100%
2	Raft/Pilinth	100%
3	1 number of Basement(s)	100%
4	0 number of Podiums	0%
5	Stilt Floor	100%
6	31 number of Slabs of Super Structure	100%
7	Internal walls, Internal Plaster, Flooring within Flats/Premises, Doors and Windows in each of the	48%
8	Sanitary Fittings within the Flat/Premises, Electrical Fittings within the Flat/premises	0%
9	Staircases, Lift Wells and Lobbies at each Floor level connecting Staircases and Lifts, Overhead and	0%
10	The external plumbing and external plaster, Elevation, completion of terraces with waterproofing of the	0%
11	Installation of lifts, water pumps, Fire Fighting Fittings and Equipments as per CFO NOC, Electrical fittings to	0%

Table B
Internal & External Development Works in Respect of the Entire Registered Phase

S No	Common Areas and Facilities, Amenities	Proposed (Yes/No)	Details	Percentage of Work done
1	Internal Roads & Footpaths	Yes		55%
2	Water Supply	Yes		0%
3	Sewerage (chamber, lines, Septic Tank, STP)	Yes		85%
4	Storm Water Drains	Yes		0%
5	Landscaping & Tree Planting	Yes		45%
6	Street Lighting	Yes		0%
7	Community Buildings	Yes		0%
8	Treatment and disposal of sewage and sullage water	Yes		50%
9	Solid Waste management & Disposal	Yes		50%
10	Water conservation, Rain water harvesting	Yes		50%
11	Energy management	NA		0%
12	Fire protection and fire safety requirements	Yes		0%
13	Electrical meter room, sub-station, receiving station	Yes		50%

Yours Faithfully

ASHU ARORA
License No. CA/2007/40332

Signature & Name (IN BLOCK LETTERS) of L.S./Architect
(License NO.....)

Regd. Office : A-15, Pamposh Enclave, G.K.-1, Outer Ring Road, New Delhi -110048, India
CIN/LLPIN - U45201DL1985 PT C021337 Tel.: +91-11-26442050 Fax : +91-11-26442035
Email : info@arcop.co.in Website : www.arcop.co.in