

Construction Progress Report

Period:

TABLE-A

Sr. No	Tasks/Activity	Percentage of work done
1	Excavation	100%
2	2 number of Basement(s) and Plinth	100%
3	0 number of Podiums	NA
4	Stilt Floor	NA
5	15 number of Slabs of Super Structure	68.96% (AS PER AREA)
6	Internal Walls, Internal Plaster, Floorings within Flats/Premises, Doors and Windows to each of the Flat/Premises.	40% (FLOOR WISE)
7	Sanitary Fittings within the Flat/Premises, Electrical Fittings within the Flat/Premises.	NOT YET STARTED
8	Staircases, Lifts Wells and Lobbies at each Floor level connecting Staircases and Lifts, Overhead and Underground Water Tanks.	58%
9	The external plumbing and external plaster, elevation, completion of terraces with waterproofing of the Building/Wing.	NOT YET STARTED
10	Installation of lifts, water pumps, Fire Fighting Fittings and Equipment as per CFO NOC, Electrical fittings to Common Areas, electro, mechanical equipment, Compliance to conditions of environment /CRZ NOC, Finishing to entrance lobby/s, plinth protection, paving of areas appurtenant to Building/Wing, Compound Wall and all other requirements as may be required to obtain Occupation / Completion Certificate.	NOT YET STARTED



TABLE-B

Sr. No	Common areas and Facilities Amenities	Proposed (yes/No)	%AGE WORKDONE	
1	Internal Roads & Footh-paths.	YES	NOT YET STARTED	
2	Water Supply	YES	NOT YET STARTED	
3	Sewarage (chamber, lines, Septic Tank , STP).	YES	92%	
4	Storm Water Drains	YES	90%	
5	Landscaping& Tree Planting	YES	NOT YET STARTED	
6	Street Lighting	YES	NOT YET STARTED	
7	Community Buildings	YES	N/A	
8	Treatment and disposal of sewage and sullage water.	YES	NOT YET STARTED	
9	Solid Waste management &Disposal	YES	NOT YET STARTED	
10	Water conservation,Rain water harvesting	YES	NOT YET STARTED	
11	Energy management	YES	NOT YET STARTED	
12	Fire protection and fire safety requirements	YES	5%	
13	Electrical meter room, sub-station receiving station	YES	NOT YET STARTED	
14	Others (Option to Add more).	YES	—	

