

FORM-Q
ARCHITECT'S CERTIFICATE

(To be submitted at the time of Registration of Ongoing Project and for withdrawal of Money from Designated Account)

No. UPRERAPRJ745601/PR-PH1/2024-25/Q1/ARCH-20

Date: 30th June 2024

Subject: Certificate of Percentage of Completion of Construction Work of 11 No. of Building(s)/Block(s) of the Godrej Palm Retreat - Phase 1 [UPRERA Registration Number - UPRERAPRJ745601] situated on the Khasra No/ Plot no SC-02F, Sector-150, Noida Demarcated by its boundaries (latitude and longitude of the end points) 28260525N to the North 28255420N to the South 77290094E to the East 77290214E to the West of village - Gautam Buddha Nagar Tehsil - Gautam Buddha Nagar Competent/ Development authority District- Gautam Buddha Nagar, Noida PIN 201301 admeasuring 33500 Sq.mts. area being developed by ACE Infracity Pvt Ltd.

We M/s **AMDD Designs** have undertaken assignment as Architect/Licensed Surveyor of certifying Percentage of Completion Work of the 11 Building(s)/Block/ Tower (s) of Godrej Palm Retreat - Phase 1, situated on the Khasra No/ Plot no SC-02F, Sector-150, Noida of village Gautam Buddha Nagar tehsil Gautam Buddha Nagar competent/ development authority District Gautam Buddha Nagar PIN 201301 admeasuring 33500 Sq.mts. area being developed by ACE Infracity Pvt Ltd.

1. Following technical professionals are appointed by owner / Promotor:

- (i) M/s AMDD Designs as L.S./ Architect;
- (ii) M/s Dr Kelkar Designs Pvt Ltd as Structural Consultant
- (ii) M/s Sunil Nayyar Consulting Engineers LLP as MEP Consultant

Based on **Site Inspection done on 30th Jun 2024**, with respect to each of the Buildings/Blocks /Towers of the aforesaid Real Estate Project, I certify that as on the date of this certificate, the Percentage of Work done for each of the Buildings /Blocks/Towers of the Real Estate Project as registered vide number UPRERAPRJ745601 under UPRERA is as per table A herein below. The percentage of the work executed with respect to each of the activity of the entire phase is detailed in the Table B.

Table A
Tower A1

Sr. No.	Task/Activity	Percentage Work Done
1	Site mobilization including site office & barricading	100%
2	Excavation for Basements	100%
3	P.C.C for raft & Wall	100%
4	RCC for raft foundation	100%
5	Retaining wall footing & walls	89%
6	Column up to basement slab	100%
7	Basement slab	100%
8	Stilt / GF Columns	100%
9	Stilt / GF Slab	100%
10	Floor-1 Columns / Shear Wall	100%
11	Floor-1 Slab	100%
12	Floor-2 Columns / Shear Wall	100%
13	Floor-2 Slab	100%
14	Floor-3 Columns / Shear Wall	100%

AMDD DESIGNS Flat # 38, Samachar Apt., Mayur Vihar, Phase-1 Extn., Delhi, PIN – 110091

Web: www.amdd-designs.com

Page 1 of 13

15	Floor-3 Slab	100%
16	Floor-4 Columns / Shear Wall	100%
17	Floor-4 Slab	100%
18	Floor-5 Columns / Shear Wall	100%
19	Floor-5 Slab	100%
20	Floor-6 Columns / Shear Wall	100%
21	Floor-6 Slab	100%
22	Brick Work	100%
23	Plaster	77%
24	Flooring	100%
25	Door / Window	95%
26	Internal Services	80%
27	Grill, Railing	100%
28	Electrical Works	30%
29	Internal Painting	0%
30	Fixtures	0%
31	External finishing/Painting	5%
32	Lift & Escalators	5%
33	Miscellaneous Finishing & Other Work	0%

Tower A2

Sr. No.	Task/Activity	Percentage Work Done
1	Site mobilization including site office & barricading	100%
2	Excavation for Basements	100%
3	Piling Work	100%
4	P.C.C for raft & Wall	100%
5	RCC for raft foundation	100%
6	Retaining wall footing & walls	100%
7	Column up to basement slab	100%
8	Basement slab	100%
9	Stilt / GF Columns	100%
10	Stilt / GF Slab	100%
11	Floor-1 Columns / Shear Wall	100%
12	Floor-1 Slab	100%
13	Floor-2 Columns / Shear Wall	100%
14	Floor-2 Slab	100%
15	Floor-3 Columns / Shear Wall	100%
16	Floor-3 Slab	100%
17	Floor-4 Columns / Shear Wall	100%
18	Floor-4 Slab	100%
19	Floor-5 Columns / Shear Wall	100%
20	Floor-5 Slab	100%
21	Floor-6 Columns / Shear Wall	100%


 Ar, Akshay Kr. Garg
 B. Arch
 CA/92/14746


22	Floor-6 Slab	100%	
23	Floor-7 Columns / Shear Wall	100%	
24	Floor-7 Slab	100%	
25	Floor-8 Columns / Shear Wall	100%	
26	Floor-8 Slab	100%	
27	Floor-9 Columns / Shear Wall	100%	
28	Floor-9 Slab	100%	
29	Floor-10 Columns / Shear Wall	100%	
30	Floor-10 Slab	100%	
31	Floor-11 Columns / Shear Wall	100%	
32	Floor-11 Slab	100%	
33	Floor-12 Columns / Shear Wall	100%	
34	Floor-12 Slab	100%	
35	Floor-13 Columns / Shear Wall	100%	
36	Floor-13 Slab	100%	
37	Floor-14 Columns / Shear Wall	100%	
38	Floor-14 Slab	100%	
39	Floor-15 Columns / Shear Wall	100%	
40	Floor-15 Slab	100%	
41	Floor-16 Columns / Shear Wall	100%	
42	Floor-16 Slab	100%	
43	Floor-17 Columns / Shear Wall	100%	
44	Floor-17 Slab	100%	
45	Floor-18 Columns / Shear Wall	100%	
46	Floor-18 Slab	100%	
47	Floor-19 Columns / Shear Wall	100%	
48	Floor-19 Slab	100%	
49	Floor-20 Columns / Shear Wall	100%	
50	Floor-20 Slab	100%	
51	Floor-21 Columns / Shear Wall	100%	
52	Floor-21 Slab	100%	
53	Floor-22 Columns / Shear Wall	100%	
54	Floor-22 Slab	100%	
55	Floor-23 Columns / Shear Wall	100%	
56	Floor-23 Slab	100%	
57	Floor-24 Columns / Shear Wall	100%	
58	Floor-24 Slab	100%	
59	Floor-25 Columns / Shear Wall	100%	
60	Floor-25 Slab	100%	
61	Floor-26 Columns / Shear Wall	100%	
62	Floor-26 Slab	100%	
63	Brick Work	35%	
64	Plaster	70%	


 Ar. Akshay Kr. Garg
 B. Arch
 CA/92/14746

65	Flooring	26%
66	Door / Window	10%
67	Internal Services	29%
68	Grill, Railing	80%
69	Electrical Works	20%
70	Internal Painting	0%
71	Fixtures	0%
72	External finishing/Painting	0%
73	Lift & Escalators	0%
74	Miscellaneous Finishing & Other Work	0%

Tower A3

Sr. No.	Task/Activity	Percentage Work Done
1	Site mobilization including site office & barricading	100%
2	Excavation for Basements	100%
3	P.C.C for raft & Wall	100%
4	RCC for raft foundation	100%
5	Retaining wall footing & walls	100%
6	Column up to basement slab	100%
7	Basement slab	100%
8	Stilt / GF Columns	100%
9	Stilt / GF Slab	100%
10	Floor-1 Columns / Shear Wall	100%
11	Floor-1 Slab	100%
12	Floor-2 Columns / Shear Wall	100%
13	Floor-2 Slab	100%
14	Floor-3 Columns / Shear Wall	100%
15	Floor-3 Slab	100%
16	Floor-4 Columns / Shear Wall	100%
17	Floor-4 Slab	100%
18	Floor-5 Columns / Shear Wall	100%
19	Floor-5 Slab	100%
20	Floor-6 Columns / Shear Wall	100%
21	Floor-6 Slab	100%
22	Brick Work	100%
23	Plaster	97%
24	Flooring	11%
25	Door / Window	5%
26	Internal Services	10%
27	Grill, Railing	100%
28	Electrical Works	20%
29	Internal Painting	0%
30	Fixtures	0%



Ar. Akshay Kr. Garg
B. Arch
CA/92/14746

31	External finishing/Painting	5%
32	Lift & Escalators	5%
33	Miscellaneous Finishing & Other Work	0%

Tower A4


Sr. No.	Task/Activity	Percentage Work Done
1	Site mobilization including site office & barricading	100%
2	Excavation for Basements	100%
3	P.C.C for raft & Wall	100%
4	RCC for raft foundation	100%
5	Retaining wall footing & walls	100%
6	Column up to basement slab	100%
7	Basement slab	100%
8	Stilt / GF Columns	100%
9	Stilt / GF Slab	100%
10	Floor-1 Columns / Shear Wall	100%
11	Floor-1 Slab	100%
12	Floor-2 Columns / Shear Wall	100%
13	Floor-2 Slab	100%
14	Floor-3 Columns / Shear Wall	100%
15	Floor-3 Slab	100%
16	Floor-4 Columns / Shear Wall	100%
17	Floor-4 Slab	100%
18	Floor-5 Columns / Shear Wall	100%
19	Floor-5 Slab	100%
20	Floor-6 Columns / Shear Wall	100%
21	Floor-6 Slab	100%
22	Brick Work	90%
23	Plaster	86%
24	Flooring	61%
25	Door / Window	4%
26	Internal Services	80%
27	Grill, Railing	100%
28	Electrical Works	20%
29	Internal Painting	0%
30	Fixtures	0%
31	External finishing/Painting	5%
32	Lift & Escalators	5%
33	Miscellaneous Finishing & Other Work	0%


 Ar. Akshay Kr. Garg
 B. Arch
 CA/92/14746



Tower A5

Sr. No.	Task/Activity	Percentage Work Done
1	Site mobilization including site office & barricading	100%
2	Excavation for Basements	100%
3	P.C.C for raft & Wall	100%
4	RCC for raft foundation	100%
5	Retaining wall footing & walls	100%
6	Column up to basement slab	100%
7	Basement slab	100%
8	Stilt / GF Columns	100%
9	Stilt / GF Slab	100%
10	Floor-1 Columns / Shear Wall	100%
11	Floor-1 Slab	100%
12	Floor-2 Columns / Shear Wall	100%
13	Floor-2 Slab	100%
14	Floor-3 Columns / Shear Wall	100%
15	Floor-3 Slab	100%
16	Floor-4 Columns / Shear Wall	100%
17	Floor-4 Slab	100%
18	Floor-5 Columns / Shear Wall	100%
19	Floor-5 Slab	100%
20	Floor-6 Columns / Shear Wall	100%
21	Floor-6 Slab	100%
22	Brick Work	100%
23	Plaster	100%
24	Flooring	96%
25	Door / Window	85%
26	Internal Services	80%
27	Grill, Railing	100%
28	Electrical Works	20%
29	Internal Painting	0%
30	Fixtures	0%
31	External finishing/Painting	5%
32	Lift & Escalators	5%
33	Miscellaneous Finishing & Other Work	0%


 Ar. Akshay Kr. Garg
 B. Arch
 CA/92/14746



Tower B1

Sr. No.	Task/Activity	Percentage Work Done
1	Site mobilization including site office & barricading	100%
2	Excavation for Basements	100%
3	P.C.C for raft & Wall	100%
4	RCC for raft foundation	100%
5	Retaining wall footing & walls	100%

6	Column up to basement slab	100%
7	Basement slab	100%
8	Stilt / GF Columns	100%
9	Stilt / GF Slab	100%
10	Floor-1 Columns / Shear Wall	100%
11	Floor-1 Slab	100%
12	Floor-2 Columns / Shear Wall	100%
13	Floor-2 Slab	100%
14	Floor-3 Columns / Shear Wall	100%
15	Floor-3 Slab	100%
16	Floor-4 Columns / Shear Wall	100%
17	Floor-4 Slab	100%
18	Floor-5 Columns / Shear Wall	100%
19	Floor-5 Slab	100%
20	Floor-6 Columns / Shear Wall	100%
21	Floor-6 Slab	100%
22	Brick Work	100%
23	Plaster	100%
24	Flooring	95%
25	Door / Window	90%
26	Internal Services	80%
27	Grill, Railing	100%
28	Electrical Works	20%
29	Internal Painting	0%
30	Fixtures	0%
31	External finishing/Painting	5%
32	Lift & Escalators	5%
33	Miscellaneous Finishing & Other Work	0%

Tower B2

Sr. No.	Task/Activity	Percentage Work Done
1	Site mobilization including site office & barricading	100%
2	Excavation for Basements	100%
3	P.C.C for raft & Wall	100%
4	RCC for raft foundation	100%
5	Retaining wall footing & walls	100%
6	Column up to basement slab	100%
7	Basement slab	100%
8	Stilt / GF Columns	100%
9	Stilt / GF Slab	100%
10	Floor-1 Columns / Shear Wall	100%
11	Floor-1 Slab	100%
12	Floor-2 Columns / Shear Wall	100%



Ar. Akshay Kr. Garg
B. Arch
CA/92/14746

13	Floor-2 Slab	100%
14	Floor-3 Columns / Shear Wall	100%
15	Floor-3 Slab	100%
16	Floor-4 Columns / Shear Wall	100%
17	Floor-4 Slab	100%
18	Floor-5 Columns / Shear Wall	100%
19	Floor-5 Slab	100%
20	Floor-6 Columns / Shear Wall	100%
21	Floor-6 Slab	100%
22	Brick Work	100%
23	Plaster	100%
24	Flooring	95%
25	Door / Window	90%
26	Internal Services	80%
27	Grill, Railing	100%
28	Electrical Works	20%
29	Internal Painting	0%
30	Fixtures	0%
31	External finishing/Painting	5%
32	Lift & Escalators	5%
33	Miscellaneous Finishing & Other Work	0%

Tower B3


Sr. No.	Task/Activity	Percentage Work Done
1	Site mobilization including site office & barricading	100%
2	Excavation for Basements	100%
3	P.C.C for raft & Wall	100%
4	RCC for raft foundation	100%
5	Retaining wall footing & walls	100%
6	Column up to basement slab	100%
7	Basement slab	100%
8	Stilt / GF Columns	100%
9	Stilt / GF Slab	100%
10	Floor-1 Columns / Shear Wall	100%
11	Floor-1 Slab	100%
12	Floor-2 Columns / Shear Wall	100%
13	Floor-2 Slab	100%
14	Floor-3 Columns / Shear Wall	100%
15	Floor-3 Slab	100%
16	Floor-4 Columns / Shear Wall	100%
17	Floor-4 Slab	100%
18	Floor-5 Columns / Shear Wall	100%
19	Floor-5 Slab	100%


 Ar. Akshay Kr. Garg
 B. Arch
 CA/92/14746

20	Floor-6 Columns / Shear Wall	100%
21	Floor-6 Slab	100%
22	Brick Work	100%
23	Plaster	70%
24	Flooring	45%
25	Door / Window	3%
26	Internal Services	80%
27	Grill, Railing	100%
28	Electrical Works	20%
29	Internal Painting	0%
30	Fixtures	0%
31	External finishing/Painting	5%
32	Lift & Escalators	5%
33	Miscellaneous Finishing & Other Work	0%


Tower B4

Sr. No.	Task/Activity	Percentage Work Done
1	Site mobilization including site office & barricading	100%
2	Excavation for Basements	100%
3	Piling Work	100%
4	P.C.C for raft & Wall	100%
5	RCC for raft foundation	100%
6	Retaining wall footing & walls	100%
7	Column up to basement slab	100%
8	Basement slab	100%
9	Stilt / GF Columns	100%
10	Stilt / GF Slab	100%
11	Floor-1 Columns / Shear Wall	100%
12	Floor-1 Slab	100%
13	Floor-2 Columns / Shear Wall	100%
14	Floor-2 Slab	100%
15	Floor-3 Columns / Shear Wall	100%
16	Floor-3 Slab	100%
17	Floor-4 Columns / Shear Wall	100%
18	Floor-4 Slab	100%
19	Floor-5 Columns / Shear Wall	100%
20	Floor-5 Slab	100%
21	Floor-6 Columns / Shear Wall	100%
22	Floor-6 Slab	100%
23	Floor-7 Columns / Shear Wall	100%
24	Floor-7 Slab	100%
25	Floor-8 Columns / Shear Wall	100%
26	Floor-8 Slab	100%



Ar. Akshay Kr. Garg
B. Arch
CA/92/14746

27	Floor-9 Columns / Shear Wall	100%	
28	Floor-9 Slab	100%	
29	Floor-10 Columns / Shear Wall	100%	
30	Floor-10 Slab	100%	
31	Floor-11 Columns / Shear Wall	100%	
32	Floor-11 Slab	100%	
33	Floor-12 Columns / Shear Wall	100%	
34	Floor-12 Slab	100%	
35	Floor-13 Columns / Shear Wall	100%	
36	Floor-13 Slab	100%	
37	Floor-14 Columns / Shear Wall	100%	
38	Floor-14 Slab	100%	
39	Floor-15 Columns / Shear Wall	100%	
40	Floor-15 Slab	100%	
41	Floor-16 Columns / Shear Wall	100%	
42	Floor-16 Slab	100%	
43	Floor-17 Columns / Shear Wall	100%	
44	Floor-17 Slab	100%	
45	Floor-18 Columns / Shear Wall	100%	
46	Floor-18 Slab	100%	
47	Floor-19 Columns / Shear Wall	100%	
48	Floor-19 Slab	100%	
49	Floor-20 Columns / Shear Wall	100%	
50	Floor-20 Slab	100%	
51	Floor-21 Columns / Shear Wall	100%	
52	Floor-21 Slab	100%	
53	Floor-22 Columns / Shear Wall	100%	
54	Floor-22 Slab	50%	
55	Floor-23 Columns / Shear Wall	0%	
56	Floor-23 Slab	0%	
57	Floor-24 Columns / Shear Wall	0%	
58	Floor-24 Slab	0%	
59	Floor-25 Columns / Shear Wall	0%	
60	Floor-25 Slab	0%	
61	Floor-26 Columns / Shear Wall	0%	
62	Floor-26 Slab	0%	
63	Brick Work	10%	
64	Plaster	25%	
65	Flooring	11%	
66	Door / Window	10%	
67	Internal Services	10%	
68	Grill, Railing	44%	
69	Electrical Works	15%	



Ar. Akshay Kr. Garg
B. Arch
CA/92/14746

70	Internal Painting	0%
71	Fixtures	0%
72	External finishing/Painting	0%
73	Lift & Escalators	0%
74	Miscellaneous Finishing & Other Work	0%

Tower B5

Sr. No.	Task/Activity	Percentage Work Done
1	Site mobilization including site office & barricading	100%
2	Excavation for Basements	100%
3	P.C.C for raft & Wall	100%
4	RCC for raft foundation	100%
5	Retaining wall footing & walls	100%
6	Column up to basement slab	100%
7	Basement slab	100%
8	Stilt / GF Columns	100%
9	Stilt / GF Slab	100%
10	Floor-1 Columns / Shear Wall	100%
11	Floor-1 Slab	100%
12	Floor-2 Columns / Shear Wall	100%
13	Floor-2 Slab	100%
14	Floor-3 Columns / Shear Wall	100%
15	Floor-3 Slab	100%
16	Floor-4 Columns / Shear Wall	100%
17	Floor-4 Slab	100%
18	Floor-5 Columns / Shear Wall	100%
19	Floor-5 Slab	100%
20	Floor-6 Columns / Shear Wall	100%
21	Floor-6 Slab	100%
22	Brick Work	100%
23	Plaster	78%
24	Flooring	0%
25	Door / Window	5%
26	Internal Services	5%
27	Grill, Railing	60%
28	Electrical Works	20%
29	Internal Painting	0%
30	Fixtures	0%
31	External finishing/Painting	5%
32	Lift & Escalators	5%
33	Miscellaneous Finishing & Other Work	0%



Ar. Akshay Kr. Garg
B. Arch
CAJ92114746

Tower E (Commercial)

Sr. No.	Task/Activity	Percentage Work Done
1	Site mobilization including site office & barricading	100%
2	Excavation for Basements	25%
3	P.C.C for raft & Wall	10%
4	RCC for raft foundation	10%
5	Retaining wall footing & walls	5%
6	Column up to basement slab	5%
7	Basement slab	0%
8	Stilt / GF Columns	0%
9	Stilt / GF Slab	0%
10	Floor-1 Columns / Shear Wall	0%
11	Floor-1 Slab	0%
12	Floor-2 Columns / Shear Wall	0%
13	Floor-2 Slab	0%
22	Brick Work	0%
23	Plaster	0%
24	Flooring	0%
25	Door / Window	0%
26	Internal Services	0%
27	Grill, Railing	0%
28	Electrical Works	0%
29	Internal Painting	0%
30	Fixtures	0%
31	External finishing/Painting	0%
32	Lift & Escalators	0%
33	Miscellaneous Finishing & Other Work	0%



 Ar, Akshay Kr. Garg
 B. Arch
 CA/92/14746

Table B
Internal & External Development Works in Respect of the Entire Registered Phase

S No	Common Areas and Facilities, Amenities	Proposed (Yes/No)	Details	Percentage of Work done
1	Boundary Wall	Yes		70%
2	Road Work	Yes		62%
3	Footpaths	Yes		12%
4	Water Supply Including Drinking Water Facilities	Yes		5%
5	Sewer System	Yes		80%
6	Drain	Yes		50%
7	Parks	Yes		5%
8	Tree Planting	Yes		20%
9	Design for Electric Supply Including Street Lighting	Yes		0%

10	Community Buildings	Yes		5%
11	Treatment and Disposal System of Sewage and Sullage water	Yes		45%
12	Solid Waste Management and Disposal System	Yes		0%
13	Water Conservation System	Yes		50%
14	Energy Management System Including Use of Renewable Energy	Yes		35%
15	Fire Protection and Fire Safety System	Yes		0%
16	Social Infrastructure and Other Public Amenities Including Public Health Services	Yes		0%
17	other miscellaneous work	Yes		0%




For AMDD Designs
AKSHAY KUMAR GARG
(Principal Partner)

Ar, Akshay Kr. Garg
B. Arch
CA/92/14746