



# espaces

ARCHITECTS, ENGINEERS, PLANNER  
VALUER, INTERIOR DESIGNERS

108, FIRST FLOOR  
CORPORATE CHAMBER-1  
VIBHUTI KHAND, GOMTI NAGAR  
LUCKNOW-226 010, PHONE : 0522-4065958  
e-mail : espaces.arch@gmail.com

FORM-Q

## ARCHITECT'S CERTIFICATE

No.....

Date: 31.12.2021

**Subject: Certificate of Percentage of Completion of Construction Work of Eldeco Uday/Joy at REGALIA Eldeco Joy-40 no. + Eldeco Uday -40 no. of Plots/Building(s)/ TWO BLOCKS [UPRERA Registration Number- UPRERAPRJ471477] situated on the Khasra No/ Plot no- 694/697 Eldeco Uday/Eldeco Joy, Eldeco Regalia & Others Demarcated by its boundaries (latitude and longitude of the end points) 26°55'46.7" N to the North 80°54'43.8" E to the South 26°55'46.7" N to the East 80°54'43.8" E to the West of village Muttakipur/Allu Nagar Diguria, Off I.I. M. Road Tehsil Lucknow Competent/ Development authority LDA District LUCKNOW PIN 226201 admeasuring 1942 sq.mts. area being developed by [Promotor's Name]- **Eldeco Housing & Industries Ltd.****

I/We ESPACES have undertaken assignment as Architect/Licensed Surveyor of certifying Percentage of Completion Work of the Eldeco Uday/Joy Plots/Building(s) of the Project, situated on the Khasra No/ Plot no. 694, 697 of village Muttakipur/Allu Nagar Diguria, Off I.I. M. Road tehsil Lucknow competent/ development authority LDA District LUCKNOW PIN 226201 admeasuring 1942sq.mts. area being developed by [Promotor's Name]- **Eldeco Housing & Industries Ltd.**

1. Following technical professionals are appointed by owner / Promotor :-

- (i) M/s/Shri/Smt SANJAY KUMAR GUPTA as L.S. / Architect ;
- (ii) M/s/Shri/Smt ATS Structural Consultants as Structural Consultant
- (iii) M/s/Shri/Smt Paradise Consultant as MEP Consultant
- (iv) M/s/Shri/Smt Anil Rai as Site Supervisor

Based on Site Inspection, with respect to each of the Buildings /Blocks/Towers of the aforesaid Real Estate Project, I certify that as on the date of this certificate, the Percentage of Work done for each of the Buildings /Blocks/Towers of the Real Estate Project as registered vide number UPRERAPRJ471477 under UPRERA is as per table A herein below. The percentage of the work executed with respect to each of the activity of the entire phase is detailed in the Table B.

Table A

| Sr. No. | Task/Activity                                                                                                                                                                                                                                                                                                                                                                                                                  | Percentage Work Done |
|---------|--------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|----------------------|
| 1       | Excavation                                                                                                                                                                                                                                                                                                                                                                                                                     | 100.00%              |
| 2       | _____ number of Basement(s) and Plinth                                                                                                                                                                                                                                                                                                                                                                                         | N.A.                 |
| 3       | _____ number of Podiums                                                                                                                                                                                                                                                                                                                                                                                                        | N.A.                 |
| 4       | Stilt Floor                                                                                                                                                                                                                                                                                                                                                                                                                    | N.A.                 |
| 5       | Slabs of Super Structure                                                                                                                                                                                                                                                                                                                                                                                                       | 100.00%              |
| 6       | Internal walls, Internal Plaster, Flooring within Flats/Premises, Doors and Windows in each of the Flats/Premises                                                                                                                                                                                                                                                                                                              | 100.00%              |
| 7       | Sanitary Fittings within the Flat/Premises, Electrical Fittings within the Flat/premises                                                                                                                                                                                                                                                                                                                                       | 100.00%              |
| 8       | Staircases, Lift Wells and Lobbies at each Floor level connecting Staircases and Lifts, Overhead and Underground Water Tanks                                                                                                                                                                                                                                                                                                   | 100.00%              |
| 9       | The external plumbing and external plaster, Elevation, completion of terraces with waterproofing of the Building /Block/Tower                                                                                                                                                                                                                                                                                                  | 100.00%              |
| 10      | Installation of lifts, water pumps, Fire Fighting Fittings and Equipments as per CFO NOC, Electrical fittings to Common Areas, electro-mechanical equipments, Compliance to conditions of environment/CRZ NOC, Finishing to entrance lobby/s, plinth protection, paving of areas appurtenant to Building /Block/Tower, Compound Wall and all other requirements as may be required to obtain Occupation/Completion Certificate | N.A.                 |

Table B

## Internal &amp; External Development Works in Respect of the Entire Registered Phase

| S No | Common Areas and Facilities, Amenities      | Proposed (Yes/No) | Details | Percentage of Work done |
|------|---------------------------------------------|-------------------|---------|-------------------------|
| 1    | Internal Roads & Footpaths                  |                   |         | 100.00%                 |
| 2    | Water Supply                                |                   |         | 100.00%                 |
| 3    | Sewerage (chamber, lines, Septic Tank, STP) |                   |         | 100.00%                 |

31.12.21