

ARCHITECT'S CERTIFICATE

FORM-REG-1

(To be submitted at the time of Registration of Ongoing Project and for withdrawal of Money from Designated Account)

No. 1

Date: 30.06.2022

Subject:	Certificate of Percentage of Completion of Construction Work of 09 No. of Building(s)/Block(s) of the Project "Gaur Siddhartham", UPRERAPRJ3935 situated on Plot no-8, BS-01 Siddhartha Vihar Yojna, Ghaziabad (U.P), Demarcated by its boundaries (latitude and longitude of the end points) 28°39' 11.85"N, 28°39' 24.57"N, 77°24' 19.64"E, 77°24' 16.79"E of Tehsil Ghaziabad, Competent/ Development authority AWAS VIKAS PARISHAD, PIN: 201009 admeasuring 48750 sq.mts. area being developed by M/s Gaursons India Pvt. Ltd. I, Hariom Shukla, has undertaken assignment as Architect of certifying Percentage of Completion of Construction Work of 09 No. of Building(s)/Block(s) of the Project "Gaur Siddhartham", UPRERAPRJ3935 situated on Plot no-8, BS-01 Siddhartha Vihar Yojna, Ghaziabad (U.P), Demarcated by its boundaries (latitude and longitude of the end points) 28°39' 11.85"N, 28°39' 24.57"N, 77°24' 19.64"E, 77°24' 16.79"E of Tehsil Ghaziabad, Competent/ Development authority AWAS VIKAS PARISHAD, PIN: 201009 admeasuring 48750 sq.mts. area being developed by M/s Gaursons India Pvt. Ltd. 1. Following technical professionals are appointed by owner / Promotor :- (i) Shri Hariom Shukla as Architect ; (ii) M/s Vakil Mehta Sheth (VMS) as Structural Consultant (iii) M/s CESPL Consultants as MEP Consultant (iv) Shri C M Pandey as Project Incharge
----------	---

Based on Site Inspection, with respect to each of the Buildings /Blocks/Towers of the aforesaid Real Estate Project, I certify that as on the date of this certificate, the Percentage of Work done for each of the Buildings /Blocks/Towers of the Real Estate Project as registered vide number UPRERAPRJ3935 under UPRERA is as per table A herein below. The percentage of the work executed with respect to each of the activity of the entire phase is detailed in the Table B.

Table A (Tower-A)

Sr. No.	Task/Activity	Percentage Work Done
1	Excavation	100.00%
2	2 number of Basement(s) and Plinth	100.00%
3	0 number of Podiums	100.00%
4	Stilt Floor	100.00%
5	31 number of Slabs of Super Structure	100.00%
6	Internal walls, Internal Plaster, Flooring within Flats/Premises, Doors and Windows in each of the Flats/Premises	90.00%
7	Sanitary Fittings within the Flat/Premises, Electrical Fittings within the Flat/premises	90.00%
8	Staircases, Lift Wells and Lobbies at each Floor level connecting Staircases and Lifts, Overhead and Underground Water Tanks	100.00%
9	The external plumbing and external plaster,Elevation, completion of terraces with waterproofing of the Building /Block/Tower	95.00%
10	Installation of lifts, water pumps, Fire Fighting Fittings and Equipments as per CFO NOC, Electrical fittings to Common Areas, electro-mechanical equipments, Compliance to conditions of environment/CRZ NOC, Finishing to entrance lobby/s, plinth protection, paving of areas appurtenant to Building /Block/Tower, Compound Wall and all other requirements as may be required to obtain Occupation/Completion Certificate	95.00%

Table A (Tower-B)

Sr. No.	Task/Activity	Percentage Work Done
1	Excavation	100.00%
2	2 number of Basement(s) and Plinth	100.00%
3	0 number of Podiums	100.00%
4	Stilt Floor	100.00%
5	31 number of Slabs of Super Structure	100.00%
6	Internal walls, Internal Plaster, Flooring within Flats/Premises, Doors and Windows in each of the Flats/Premises	100.00%
7	Sanitary Fittings within the Flat/Premises, Electrical Fittings within the Flat/premises	100.00%
8	Staircases, Lift Wells and Lobbies at each Floor level connecting Staircases and Lifts, Overhead and Underground Water Tanks	100.00%
9	The external plumbing and external plaster,Elevation, completion of terraces with waterproofing of the Building /Block/Tower	100.00%
10	Installation of lifts, water pumps, Fire Fighting Fittings and Equipments as per CFO NOC, Electrical fittings to Common Areas, electro-mechanical equipments, Compliance to conditions of environment/CRZ NOC, Finishing to entrance lobby/s, plinth protection, paving of areas appurtenant to Building /Block/Tower, Compound Wall and all other requirements as may be required to obtain Occupation/Completion Certificate	100.00%

Table A (Tower-C)

Sr. No.	Task/Activity	Percentage Work Done
1	Excavation	100.00%
2	2 number of Basement(s) and Plinth	100.00%
3	0 number of Podiums	100.00%
4	Stilt Floor	100.00%
5	31 number of Slabs of Super Structure	100.00%
6	Internal walls, Internal Plaster, Flooring within Flats/Premises, Doors and Windows in each of the Flats/Premises	60.00%
7	Sanitary Fittings within the Flat/Premises, Electrical Fittings within the Flat/premises	75.00%
8	Staircases, Lift Wells and Lobbies at each Floor level connecting Staircases and Lifts, Overhead and Underground Water Tanks	85.00%

(Signature)

9	The external plumbing and external plaster,Elevation, completion of terraces with waterproofing of the Building /Block/Tower	65.00%
10	Installation of lifts, water pumps, Fire Fighting Fittings and Equipments as per CFO NOC, Electrical fittings to Common Areas, electro-mechanical equipments, Compliance to conditions of environment/CRZ NOC, Finishing to entrance lobby/s, plinth protection, paving of areas appurtenant to Building /Block/Tower, Compound Wall and all other requirements as may be required to obtain Occupation/Completion Certificate	50.00%

Table A (Tower-D)

Sr. No.	Task/Activity	Percentage Work Done
1	Excavation	100.00%
2	2 number of Basement(s) and Plinth	100.00%
3	0 number of Podiums	100.00%
4	Stilt Floor	100.00%
5	31 number of Slabs of Super Structure	100.00%
6	Internal walls, Internal Plaster, Flooring within Flats/Premises, Doors and Windows in each of the Flats/Premises	90.00%
7	Sanitary Fittings within the Flat/Premises, Electrical Fittings within the Flat/premises	85.00%
8	Staircases, Lift Wells and Lobbies at each Floor level connecting Staircases and Lifts, Overhead and Underground Water Tanks	90.00%
9	The external plumbing and external plaster,Elevation, completion of terraces with waterproofing of the Building /Block/Tower	85.00%
10	Installation of lifts, water pumps, Fire Fighting Fittings and Equipments as per CFO NOC, Electrical fittings to Common Areas, electro-mechanical equipments, Compliance to conditions of environment/CRZ NOC, Finishing to entrance lobby/s, plinth protection, paving of areas appurtenant to Building /Block/Tower, Compound Wall and all other requirements as may be required to obtain Occupation/Completion Certificate	90.00%

Table A (Tower-E)

Sr. No.	Task/Activity	Percentage Work Done
1	Excavation	100.00%
2	2 number of Basement(s) and Plinth	100.00%
3	0 number of Podiums	100.00%
4	Stilt Floor	100.00%
5	31 number of Slabs of Super Structure	100.00%
6	Internal walls, Internal Plaster, Flooring within Flats/Premises, Doors and Windows in each of the Flats/Premises	90.00%
7	Sanitary Fittings within the Flat/Premises, Electrical Fittings within the Flat/premises	85.00%
8	Staircases, Lift Wells and Lobbies at each Floor level connecting Staircases and Lifts, Overhead and Underground Water Tanks	90.00%
9	The external plumbing and external plaster,Elevation, completion of terraces with waterproofing of the Building /Block/Tower	85.00%
10	Installation of lifts, water pumps, Fire Fighting Fittings and Equipments as per CFO NOC, Electrical fittings to Common Areas, electro-mechanical equipments, Compliance to conditions of environment/CRZ NOC, Finishing to entrance lobby/s, plinth protection, paving of areas appurtenant to Building /Block/Tower, Compound Wall and all other requirements as may be required to obtain Occupation/Completion Certificate	80.00%

Table A (Tower-F)

Sr. No.	Task/Activity	Percentage Work Done
1	Excavation	100.00%
2	2 number of Basement(s) and Plinth	100.00%
3	0 number of Podiums	100.00%
4	Stilt Floor	100.00%
5	31 number of Slabs of Super Structure	100.00%
6	Internal walls, Internal Plaster, Flooring within Flats/Premises, Doors and Windows in each of the Flats/Premises	90.00%
7	Sanitary Fittings within the Flat/Premises, Electrical Fittings within the Flat/premises	85.00%
8	Staircases, Lift Wells and Lobbies at each Floor level connecting Staircases and Lifts, Overhead and Underground Water Tanks	90.00%
9	The external plumbing and external plaster,Elevation, completion of terraces with waterproofing of the Building /Block/Tower	85.00%
10	Installation of lifts, water pumps, Fire Fighting Fittings and Equipments as per CFO NOC, Electrical fittings to Common Areas, electro-mechanical equipments, Compliance to conditions of environment/CRZ NOC, Finishing to entrance lobby/s, plinth protection, paving of areas appurtenant to Building /Block/Tower, Compound Wall and all other requirements as may be required to obtain Occupation/Completion Certificate	80.00%

Table A (Tower-G)

Sr. No.	Task/Activity	Percentage Work Done
1	Excavation	100.00%
2	2 number of Basement(s) and Plinth	100.00%
3	0 number of Podiums	100.00%
4	Stilt Floor	100.00%
5	31 number of Slabs of Super Structure	100.00%
6	Internal walls, Internal Plaster, Flooring within Flats/Premises, Doors and Windows in each of the Flats/Premises	98.00%
7	Sanitary Fittings within the Flat/Premises, Electrical Fittings within the Flat/premises	98.00%

Geometric Park, Plot No. 1
 Abbey Road-II, Indrapuram, Gzb.

8	Staircases, Lift Wells and Lobbies at each Floor level connecting Staircases and Lifts, Overhead and Underground Water Tanks	100.00%
9	The external plumbing and external plaster,Elevation, completion of terraces with waterproofing of the Building /Block/Tower	100.00%
10	Installation of lifts, water pumps, Fire Fighting Fittings and Equipments as per CFO NOC, Electrical fittings to Common Areas, electro-mechanical equipments, Compliance to conditions of environment/CRZ NOC, Finishing to entrance lobby/s, plinth protection, paving of areas appurtenant to Building /Block/Tower, Compound Wall and all other requirements as may be required to obtain Occupation/Completion Certificate	100.00%

Table A (Tower-H)

Sr. No.	Task/Activity	Percentage Work Done
1	Excavation	100.00%
2	2 number of Basement(s) and Plinth	100.00%
3	0 number of Podiums	100.00%
4	Stilt Floor	100.00%
5	31 number of Slabs of Super Structure	100.00%
6	Internal walls, Internal Plaster, Flooring within Flats/Premises, Doors and Windows in each of the Flats/Premises	100.00%
7	Sanitary Fittings within the Flat/Premises, Electrical Fittings within the Flat/premises	100.00%
8	Staircases, Lift Wells and Lobbies at each Floor level connecting Staircases and Lifts, Overhead and Underground Water Tanks	100.00%
9	The external plumbing and external plaster,Elevation, completion of terraces with waterproofing of the Building /Block/Tower	100.00%
10	Installation of lifts, water pumps, Fire Fighting Fittings and Equipments as per CFO NOC, Electrical fittings to Common Areas, electro-mechanical equipments, Compliance to conditions of environment/CRZ NOC, Finishing to entrance lobby/s, plinth protection, paving of areas appurtenant to Building /Block/Tower, Compound Wall and all other requirements as may be required to obtain Occupation/Completion Certificate	100.00%

Table A (Tower-I)

Sr. No.	Task/Activity	Percentage Work Done
1	Excavation	100.00%
2	2 number of Basement(s) and Plinth	100.00%
3	0 number of Podiums	100.00%
4	Stilt Floor	100.00%
5	31 number of Slabs of Super Structure	100.00%
6	Internal walls, Internal Plaster, Flooring within Flats/Premises, Doors and Windows in each of the Flats/Premises	98.00%
7	Sanitary Fittings within the Flat/Premises, Electrical Fittings within the Flat/premises	98.00%
8	Staircases, Lift Wells and Lobbies at each Floor level connecting Staircases and Lifts, Overhead and Underground Water Tanks	100.00%
9	The external plumbing and external plaster,Elevation, completion of terraces with waterproofing of the Building /Block/Tower	100.00%
10	Installation of lifts, water pumps, Fire Fighting Fittings and Equipments as per CFO NOC, Electrical fittings to Common Areas, electro-mechanical equipments, Compliance to conditions of environment/CRZ NOC, Finishing to entrance lobby/s, plinth protection, paving of areas appurtenant to Building /Block/Tower, Compound Wall and all other requirements as may be required to obtain Occupation/Completion Certificate	100.00%

Table B


Internal & External Development Works in Respect of the Entire Registered Phase

S No	Common Areas and Facilities, Amenities	Proposed (Yes/No)	Details	Percentage of Work done
1	Internal Roads & Footpaths	Yes	Internal Roads & Footpaths workt in progress	95.00%
2	Water Supply	Yes	Water Supply work is done	100.00%
3	Sewarage (chamber, lines, Septic Tank, STP)	Yes	Sewarage (chamber, lines, Septic Tank, STP)work is done	100.00%
4	Strom Water Drains	Yes	Strom Water Drains work is done	100.00%
5	Landscaping & Tree Planting	Yes	Internal Roads & Footpaths work is done	70.00%
6	Street Lighting	Yes	Street Lighting work is done	100.00%
7	Community Buildings	Yes	Community Buildings work are in progress	75.00%
8	Treatment and disposal of sewage and sullage water	Yes	Treatment and disposal of sewage and sullage water work are in progress	75.00%
9	Solid Waste management & Disposal	Yes	Solid Waste management & Disposal work are in progress	85.00%
10	Water conservation, Rain water harvesting	Yes	Water conservation, Rain water harvesting work is done	100.00%
11	Energy management	Yes	Energy management work are not in progress	0.00%
12	Fire protection and fire safety requirements	Yes	Fire protection and fire safety requirements work are in progress	95.00%
13	Electrical meter room, sub-station, receiving station	Yes	Electrical meter room, sub-station, receiving station work are in progress	95.00%

CA/2012/554-10
Gaur Biz Park, Plot No.
Abhay Khand-II, Indrapuram, G2b

14	Other (Option to Add more)	N.A	0.00%
----	----------------------------	-----	-------

Yours Faithfully



AR. HARIOM SHUKLA
(License No. CA/2012/55413)

HARIOM SHUKLA
ARCHITECT
CA/2012/55413
Gaur Biz Park, Plot No. 1
Abhay Khand-II, Indrapuram, Gzb.

GAUR BIZ PARK, PLOT NO-01, ABHAY KHAND II, INDIRAPURAM, GHAZIABAD (U.P)-201014