

ARCHITECT'S CERTIFICATE

(To be submitted at the time of Registration of Ongoing Project and for withdrawal of Money from Designated Account)

No. 1

Date: 14.01.2025

Subject: Certificate of Percentage of Completion of Construction Work of 09 No. of Building(s)/Block(s) of the Project "The Islands" / "Condominium Apartments-B11", situated on Plot no : B-11 at Jaypee Greens, Surajpur Kasma Road, Sector 19 & 25, Greater Noida, Gautam Buddh Nagar, (U.P). Demarcated end points of project - Latitude : 28.467302 & Longitude : 77.510531 of Tehsil Dadri, Competent/ Development authority GNIDA, District Gautam Buddha Nagar, PIN: 201306, admeasuring 9018 sq.mts. area being developed by M/s Gaursons India Pvt. Ltd.

I, Ateesh Aggarwal, has undertaken assignment as Architect of certifying Percentage of Completion of Construction Work of 09 No. of Building(s)/Block(s) of the Project "The Islands" / "Condominium Apartments-B11" situated on Plot no- B-11, at Jaypee Greens, Surajpur Kasma Road, , Sector 19 & 25, Greater Noida, Gautam Buddh Nagar, (U.P), Demarcated end points of project - Latitude : 28.467302 & Longitude : 77.510531 of Tehsil Dadri, Competent/ Development authority GNIDA, District Gautam Buddha Nagar, PIN: 201306, admeasuring 9018 sq.mts. area being developed by M/s Gaursons India Pvt. Ltd.

1. Following technical professionals are appointed by owner / Promotor :-

- (i) Shri Ateesh Agarwal (Atwin) as Architect
- (ii) M/s RD CONSULTANTS as Structural Consultant
- (iii) M/s CESPL Consultants as MEP Consultant
- (iv) Shri Anand Singh as Project Incharge

Based on Site Inspection, with respect to each of the Buildings /Blocks/Towers of the aforesaid Real Estate Project, I certify

Table A (Tower-A)

Sr. No.	Task/Activity	Percentage Work Done
1	Excavation	100.00%
2	2 number of Basement(s) and Plinth	100.00%
3	0 number of Podiums	100.00%
4	Stilt Floor	100.00%
5	31 number of Slabs of Super Structure	35.00%
6	Internal walls, Internal Plaster, Flooring within	35.00%
7	Sanitary Fittings within the Flat/Premises, Electrical	0.00%
8	Staircases, Lift Wells and Lobbies at each Floor level	35.00%
9	The external plumbing and external plaster,Elevation,	0.00%
10	Installation of lifts, water pumps, Fire Fighting Fittings and	0.00%

Table A (Tower-B)

Sr. No.	Task/Activity	Percentage Work Done
1	Excavation	100.00%
2	2 number of Basement(s) and Plinth	100.00%
3	0 number of Podiums	100.00%
4	Stilt Floor	100.00%
5	31 number of Slabs of Super Structure	20.00%
6	Internal walls, Internal Plaster, Flooring within	20.00%
7	Sanitary Fittings within the Flat/Premises, Electrical	0.00%
8	Staircases, Lift Wells and Lobbies at each Floor level	20.00%
9	The external plumbing and external plaster,Elevation,	0.00%
10	Installation of lifts, water pumps, Fire Fighting Fittings and	0.00%

Table A (Tower-C)

Sr. No.	Task/Activity	Percentage Work Done
1	Excavation	100.00%
2	2 number of Basement(s) and Plinth	100.00%
3	0 number of Podiums	100.00%
4	Stilt Floor	100.00%

AR. ATEESH AGGARWAL
B.Arch, B.Sc. (Hons) (LONDON)
F.I.C.I. V - 2003/1-2-1879
M.C.A. - 2003/1-2-1879

5	31 number of Slabs of Super Structure	20.00%
6	Internal walls, Internal Plaster, Flooring within	20.00%
7	Sanitary Fittings within the Flat/Premises, Electrical	0.00%
8	Staircases, Lift Wells and Lobbies at each Floor level	20.00%
9	The external plumbing and external plaster,Elevation,	0.00%
10	Installation of lifts, water pumps, Fire Fighting Fittings and	0.00%

Table A (Tower-D)

Sr. No.	Task/Activity	Percentage Work Done
1	Excavation	100.00%
2	2 number of Basement(s) and Plinth	100.00%
3	0 number of Podiums	100.00%
4	Stilt Floor	100.00%
5	31 number of Slabs of Super Structure	3.00%
6	Internal walls, Internal Plaster, Flooring within	3.00%
7	Sanitary Fittings within the Flat/Premises, Electrical	0.00%
8	Staircases, Lift Wells and Lobbies at each Floor level	3.00%
9	The external plumbing and external plaster,Elevation,	0.00%
10	Installation of lifts, water pumps, Fire Fighting Fittings and	0.00%

Table A (Tower-E)

Sr. No.	Task/Activity	Percentage Work Done
1	Excavation	100.00%
2	2 number of Basement(s) and Plinth	100.00%
3	0 number of Podiums	100.00%
4	Stilt Floor	100.00%
5	31 number of Slabs of Super Structure	3.00%
6	Internal walls, Internal Plaster, Flooring within	3.00%
7	Sanitary Fittings within the Flat/Premises, Electrical	0.00%
8	Staircases, Lift Wells and Lobbies at each Floor level	3.00%
9	The external plumbing and external plaster,Elevation,	0.00%
10	Installation of lifts, water pumps, Fire Fighting Fittings and	0.00%

Table A (Tower-F)

Sr. No.	Task/Activity	Percentage Work Done
1	Excavation	100.00%
2	2 number of Basement(s) and Plinth	100.00%
3	0 number of Podiums	100.00%
4	Stilt Floor	100.00%
5	31 number of Slabs of Super Structure	18.00%
6	Internal walls, Internal Plaster, Flooring within	18.00%
7	Sanitary Fittings within the Flat/Premises, Electrical	0.00%
8	Staircases, Lift Wells and Lobbies at each Floor level	18.00%
9	The external plumbing and external plaster,Elevation,	0.00%
10	Installation of lifts, water pumps, Fire Fighting Fittings and	0.00%

Table A (Tower-G)

Sr. No.	Task/Activity	Percentage Work Done
1	Excavation	100.00%
2	2 number of Basement(s) and Plinth	100.00%
3	0 number of Podiums	100.00%
4	Stilt Floor	100.00%
5	31 number of Slabs of Super Structure	18.00%
6	Internal walls, Internal Plaster, Flooring within	18.00%
7	Sanitary Fittings within the Flat/Premises, Electrical	0.00%
8	Staircases, Lift Wells and Lobbies at each Floor level	18.00%
9	The external plumbing and external plaster,Elevation,	0.00%
10	Installation of lifts, water pumps, Fire Fighting Fittings and	0.00%

Table A (Tower-H)

AR. TEESAGARWAL
B.A. (HON.) IN M.C.A. LONDON
F.T.I. - 7-CAN-1879
M.C.A. - 2013/1212.

Sr. No.	Task/Activity	Percentage Work Done
1	Excavation	100.00%
2	2 number of Basement(s) and Plinth	100.00%
3	0 number of Podiums	100.00%
4	Stilt Floor	100.00%
5	31 number of Slabs of Super Structure	4.00%
6	Internal walls, Internal Plaster, Flooring within	4.00%
7	Sanitary Fittings within the Flat/Premises, Electrical	0.00%
8	Staircases, Lift Wells and Lobbies at each Floor level	4.00%
9	The external plumbing and external plaster,Elevation,	0.00%
10	Installation of lifts, water pumps, Fire Fighting Fittings and	0.00%

Table A (Tower-I)

Sr. No.	Task/Activity	Percentage Work Done
1	Excavation	100.00%
2	2 number of Basement(s) and Plinth	100.00%
3	0 number of Podiums	75.00%
4	Stilt Floor	75.00%
5	31 number of Slabs of Super Structure	0.00%
6	Internal walls, Internal Plaster, Flooring within	0.00%
7	Sanitary Fittings within the Flat/Premises, Electrical	0.00%
8	Staircases, Lift Wells and Lobbies at each Floor level	3.00%
9	The external plumbing and external plaster,Elevation,	0.00%
10	Installation of lifts, water pumps, Fire Fighting Fittings and	0.00%

Table B

Internal & External Development Works in Respect of the Entire Registered Phase

S No	Common Areas and Facilities, Amenities	Proposed (Yes/No)	Details	Percentage of Work done
1	Internal Roads & Footpaths	Yes	Internal Roads & Footpaths work are not in progress	50.00%
2	Water Supply	Yes	Water Supply work are not in progress	50.00%
3	Sewerage (chamber, lines, Septic Tank, STP)	Yes	Sewerage (chamber, lines, Septic Tank, STP)work are not in progress	40.00%
4	Strom Water Drains	Yes	Strom Water Drains work are not in progress	30.00%
5	Landscaping & Tree Planting	Yes	Internal Roads & Footpaths work are not in progress	10.00%
6	Street Lighting	Yes	Street Lighting work are not in progress	40.00%
7	Community Buildings	Yes	Community Buildings work are not in progress	20.00%

AR. ATEESH AGARWAL
 S. ARCHITECT (MGM LONDON)
 F.I.T.V. CAPITAL 87
 M.C.A. - 2003/31212

8	Treatment and disposal of sewage and sullage water	Yes	Treatment and disposal of sewage and sullage water work are not in progress	5.00%
9	Solid Waste management & Disposal	Yes	Solid Waste management & Disposal work are not in progress	20.00%
10	Water conservation, Rain water harvesting	Yes	Water conservation, Rain water harvesting work are not in progress	5.00%
11	Energy management	Yes	Energy management work are not in progress	0.00%
12	Fire protection and fire safety requirements	Yes	Fire protection and fire safety requirements work are not in progress	10.00%
13	Electrical meter room, sub-station, receiving station	Yes	Electrical meter room, sub-station, receiving station work are not in progress	40.00%
14	Other (Option to Add more)	N.A		30.00%

Yours Faithfully

AR. ATEESH AGGARWAL
 B.ARCCL, DIP. PMT, MGMT (LONDON)
 F-89, GREEN PARK, NEW DELHI-110016

AR. ATEESH AGGARWAL
 (License No. CA/2003/31212)

F-89, GREEN PARK, NEW DELHI-110016