

ARCHITECT'S CERTIFICATE

FORM-REG 1

(To be submitted at the time of Registration of Ongoing Project and for withdrawal of Money from Designated Account)

No. 1

Date: 31.03.2022

Subject: Certificate of Percentage of Completion of Construction Work of 37 No. of Building(s)/Block(s) of the Project "16th Parkview", UPRERAPRJ6801 situated on the Plot Gaur Yamuna City (Pocket-3), Mirzapur Site (LFD-3), Sector-19, YEIDA, Greater Noida (U.P), Demarcated by its boundaries (latitude and longitude of the end points) 28°18'17.98"N, 77°33'42.50"E, 28°18'10.58"N, 77°33'52.87"E of village Mirzapur, Tehsil Gautam Buddha Nagar, Competent/ Development authority YEIDA, District Gautam Buddha Nagar, PIN: 203201 admeasuring 87756 sq.mts. area being developed by M/S Gaursons Realtech Pvt. Ltd.

I, Prabira Jena, has undertaken assignment as Architect of certifying Percentage of Completion Work of the 37 No. of Building(s)/Block(s) of the Project "16th Parkview", situated on the Plot Gaur Yamuna City (Pocket-3), Mirzapur Site (LFD-3), Sector-19, YEIDA, Greater Noida (U.P) of village Mirzapur, tehsil Gautam Buddha Nagar, competent/ development authority YEIDA, District Gautam Buddha Nagar, PIN: 203201, admeasuring 87756 sq.mts. area being developed by M/S Gaursons Realtech Pvt. Ltd.

1. Following technical professionals are appointed by owner / Promotor :-

- (i) Shri Prabira Jena as Architect ;
- (ii) M/s Vakil Mehta Sheth (VMS) as Structural Consultant
- (iii) M/s CESPL as MEP Consultant
- (iv) Shri Arvind as Site Supervisor

Based on Site Inspection, with respect to each of the Buildings /Blocks/Towers of the aforesaid Real Estate Project, I certify that as on the date of this certificate, the Percentage of Work done for each of the Buildings /Blocks/Towers of the Real Estate Project as registered vide number UPRERAPRJ6801 under UPRERA is as per table A herein below. The percentage of the work executed with respect to each of the activity of the entire phase is detailed in the Table B.

Table A (Block-A)

Sr. No.	Task/Activity	Percentage Work Done
1	Excavation	100.00%
2	1 number of Basement(s) and Plinth	100.00%
3	1 number of Podiums	100.00%
4	Stilt Floor	100.00%
5	24 number of Slabs of Super Structure	100.00%
6	Internal walls, Internal Plaster, Flooring within Flats/Premises, Doors and Windows in each of the Flats/Premises	100.00%
7	Sanitary Fittings within the Flat/Premises, Electrical Fittings within the Flat/premises	100.00%
8	Staircases, Lift Wells and Lobbies at each Floor level connecting Staircases and Lifts, Overhead and Underground Water Tanks	100.00%
9	The external plumbing and external plaster,Elevation, completion of terraces with waterproofing of the Building /Block/Tower	100.00%
10	Installation of lifts, water pumps, Fire Fighting Fittings and Equipments as per CFO NOC, Electrical fittings to Common Areas, electro-mechanical equipments, Compliance to conditions of environment/CRZ NOC, Finishing to entrance lobby/s, plinth protection, paving of areas appurtenant to Building /Block/Tower, Compound Wall and all other requirements as may be required to obtain Occupation/Completion Certificate	100.00%

Table A (Block-B)

Sr. No.	Task/Activity	Percentage Work Done
1	Excavation	100.00%
2	1 number of Basement(s) and Plinth	100.00%
3	1 number of Podiums	100.00%
4	Stilt Floor	100.00%
5	24 number of Slabs of Super Structure	100.00%
6	Internal walls, Internal Plaster, Flooring within Flats/Premises, Doors and Windows in each of the Flats/Premises	100.00%
7	Sanitary Fittings within the Flat/Premises, Electrical Fittings within the Flat/premises	100.00%
8	Staircases, Lift Wells and Lobbies at each Floor level connecting Staircases and Lifts, Overhead and Underground Water Tanks	100.00%
9	The external plumbing and external plaster,Elevation, completion of terraces with waterproofing of the Building /Block/Tower	100.00%
10	Installation of lifts, water pumps, Fire Fighting Fittings and Equipments as per CFO NOC, Electrical fittings to Common Areas, electro-mechanical equipments, Compliance to conditions of environment/CRZ NOC, Finishing to entrance lobby/s, plinth protection, paving of areas appurtenant to Building /Block/Tower, Compound Wall and all other requirements as may be required to obtain Occupation/Completion Certificate	100.00%

Table A (Block-C)

Sr. No.	Task/Activity	Percentage Work Done
1	Excavation	100.00%
2	1 number of Basement(s) and Plinth	100.00%
3	1 number of Podiums	100.00%
4	Stilt Floor	100.00%
5	24 number of Slabs of Super Structure	100.00%
6	Internal walls, Internal Plaster, Flooring within Flats/Premises, Doors and Windows in each of the Flats/Premises	100.00%
7	Sanitary Fittings within the Flat/Premises, Electrical Fittings within the Flat/premises	100.00%

PRABIRA JENA
ARCHITECT
(CA-2000-22690)
New Delhi

8	Staircases, Lift Wells and Lobbies at each Floor level connecting Staircases and Lifts, Overhead and Underground Water Tanks	100.00%
9	The external plumbing and external plaster,Elevation, completion of terraces with waterproofing of the Building /Block/Tower	100.00%
10	Installation of lifts, water pumps, Fire Fighting Fittings and Equipments as per CFO NOC, Electrical fittings to Common Areas, electro-mechanical equipments, Compliance to conditions of environment/CRZ NOC, Finishing to entrance lobby/s, plinth protection, paving of areas appurtenant to Building /Block/Tower, Compound Wall and all other requirements as may be required to obtain Occupation/Completion Certificate	100.00%

Table A (Block-D)

Sr. No.	Task/Activity	Percentage Work Done
1	Excavation	100.00%
2	1 number of Basement(s) and Plinth	100.00%
3	1 number of Podiums	100.00%
4	Stilt Floor	100.00%
5	24 number of Slabs of Super Structure	100.00%
6	Internal walls, Internal Plaster, Flooring within Flats/Premises, Doors and Windows in each of the Flats/Premises	100.00%
7	Sanitary Fittings within the Flat/Premises, Electrical Fittings within the Flat/premises	100.00%
8	Staircases, Lift Wells and Lobbies at each Floor level connecting Staircases and Lifts, Overhead and Underground Water Tanks	100.00%
9	The external plumbing and external plaster,Elevation, completion of terraces with waterproofing of the Building /Block/Tower	100.00%
10	Installation of lifts, water pumps, Fire Fighting Fittings and Equipments as per CFO NOC, Electrical fittings to Common Areas, electro-mechanical equipments, Compliance to conditions of environment/CRZ NOC, Finishing to entrance lobby/s, plinth protection, paving of areas appurtenant to Building /Block/Tower, Compound Wall and all other requirements as may be required to obtain Occupation/Completion Certificate	100.00%

Table A (Block-E)

Sr. No.	Task/Activity	Percentage Work Done
1	Excavation	100.00%
2	1 number of Basement(s) and Plinth	100.00%
3	1 number of Podiums	100.00%
4	Stilt Floor	100.00%
5	24 number of Slabs of Super Structure	100.00%
6	Internal walls, Internal Plaster, Flooring within Flats/Premises, Doors and Windows in each of the Flats/Premises	100.00%
7	Sanitary Fittings within the Flat/Premises, Electrical Fittings within the Flat/premises	100.00%
8	Staircases, Lift Wells and Lobbies at each Floor level connecting Staircases and Lifts, Overhead and Underground Water Tanks	100.00%
9	The external plumbing and external plaster,Elevation, completion of terraces with waterproofing of the Building /Block/Tower	100.00%
10	Installation of lifts, water pumps, Fire Fighting Fittings and Equipments as per CFO NOC, Electrical fittings to Common Areas, electro-mechanical equipments, Compliance to conditions of environment/CRZ NOC, Finishing to entrance lobby/s, plinth protection, paving of areas appurtenant to Building /Block/Tower, Compound Wall and all other requirements as may be required to obtain Occupation/Completion Certificate	100.00%

Table A (Block-F)

Sr. No.	Task/Activity	Percentage Work Done
1	Excavation	100.00%
2	1 number of Basement(s) and Plinth	100.00%
3	1 number of Podiums	100.00%
4	Stilt Floor	100.00%
5	24 number of Slabs of Super Structure	100.00%
6	Internal walls, Internal Plaster, Flooring within Flats/Premises, Doors and Windows in each of the Flats/Premises	100.00%
7	Sanitary Fittings within the Flat/Premises, Electrical Fittings within the Flat/premises	100.00%
8	Staircases, Lift Wells and Lobbies at each Floor level connecting Staircases and Lifts, Overhead and Underground Water Tanks	100.00%
9	The external plumbing and external plaster,Elevation, completion of terraces with waterproofing of the Building /Block/Tower	100.00%
10	Installation of lifts, water pumps, Fire Fighting Fittings and Equipments as per CFO NOC, Electrical fittings to Common Areas, electro-mechanical equipments, Compliance to conditions of environment/CRZ NOC, Finishing to entrance lobby/s, plinth protection, paving of areas appurtenant to Building /Block/Tower, Compound Wall and all other requirements as may be required to obtain Occupation/Completion Certificate	100.00%

Table A (Block-G)

Sr. No.	Task/Activity	Percentage Work Done
1	Excavation	100.00%
2	1 number of Basement(s) and Plinth	100.00%
3	1 number of Podiums	100.00%
4	Stilt Floor	100.00%
5	24 number of Slabs of Super Structure	100.00%

PRABIR
ARCHITECT
(CA-2003-32690)
New Delhi

6	Internal walls, Internal Plaster, Flooring within Flats/Premises, Doors and Windows in each of the Flats/Premises	100.00%
7	Sanitary Fittings within the Flat/Premises, Electrical Fittings within the Flat/premises	100.00%
8	Staircases, Lift Wells and Lobbies at each Floor level connecting Staircases and Lifts, Overhead and Underground Water Tanks	100.00%
9	The external plumbing and external plaster,Elevation, completion of terraces with waterproofing of the Building /Block/Tower	100.00%
10	Installation of lifts, water pumps, Fire Fighting Fittings and Equipments as per CFO NOC, Electrical fittings to Common Areas, electro-mechanical equipments, Compliance to conditions of environment/CRZ NOC, Finishing to entrance lobby/s, plinth protection, paving of areas appurtenant to Building /Block/Tower, Compound Wall and all other requirements as may be required to obtain Occupation/Completion Certificate	100.00%

Table A (Block-H)

Sr. No.	Task/Activity	Percentage Work Done
1	Excavation	100.00%
2	1 number of Basement(s) and Plinth	100.00%
3	1 number of Podiums	100.00%
4	Stilt Floor	100.00%
5	24 number of Slabs of Super Structure	100.00%
6	Internal walls, Internal Plaster, Flooring within Flats/Premises, Doors and Windows in each of the Flats/Premises	100.00%
7	Sanitary Fittings within the Flat/Premises, Electrical Fittings within the Flat/premises	100.00%
8	Staircases, Lift Wells and Lobbies at each Floor level connecting Staircases and Lifts, Overhead and Underground Water Tanks	100.00%
9	The external plumbing and external plaster,Elevation, completion of terraces with waterproofing of the Building /Block/Tower	100.00%
10	Installation of lifts, water pumps, Fire Fighting Fittings and Equipments as per CFO NOC, Electrical fittings to Common Areas, electro-mechanical equipments, Compliance to conditions of environment/CRZ NOC, Finishing to entrance lobby/s, plinth protection, paving of areas appurtenant to Building /Block/Tower, Compound Wall and all other requirements as may be required to obtain Occupation/Completion Certificate	100.00%

Table A (Block-I)

Sr. No.	Task/Activity	Percentage Work Done
1	Excavation	100.00%
2	1 number of Basement(s) and Plinth	100.00%
3	1 number of Podiums	100.00%
4	Stilt Floor	100.00%
5	24 number of Slabs of Super Structure	100.00%
6	Internal walls, Internal Plaster, Flooring within Flats/Premises, Doors and Windows in each of the Flats/Premises	100.00%
7	Sanitary Fittings within the Flat/Premises, Electrical Fittings within the Flat/premises	100.00%
8	Staircases, Lift Wells and Lobbies at each Floor level connecting Staircases and Lifts, Overhead and Underground Water Tanks	100.00%
9	The external plumbing and external plaster,Elevation, completion of terraces with waterproofing of the Building /Block/Tower	100.00%
10	Installation of lifts, water pumps, Fire Fighting Fittings and Equipments as per CFO NOC, Electrical fittings to Common Areas, electro-mechanical equipments, Compliance to conditions of environment/CRZ NOC, Finishing to entrance lobby/s, plinth protection, paving of areas appurtenant to Building /Block/Tower, Compound Wall and all other requirements as may be required to obtain Occupation/Completion Certificate	100.00%

Table A (Block-K)

Sr. No.	Task/Activity	Percentage Work Done
1	Excavation	100.00%
2	1 number of Basement(s) and Plinth	100.00%
3	1 number of Podiums	100.00%
4	Stilt Floor	100.00%
5	24 number of Slabs of Super Structure	100.00%
6	Internal walls, Internal Plaster, Flooring within Flats/Premises, Doors and Windows in each of the Flats/Premises	100.00%
7	Sanitary Fittings within the Flat/Premises, Electrical Fittings within the Flat/premises	100.00%
8	Staircases, Lift Wells and Lobbies at each Floor level connecting Staircases and Lifts, Overhead and Underground Water Tanks	100.00%
9	The external plumbing and external plaster,Elevation, completion of terraces with waterproofing of the Building /Block/Tower	100.00%
10	Installation of lifts, water pumps, Fire Fighting Fittings and Equipments as per CFO NOC, Electrical fittings to Common Areas, electro-mechanical equipments, Compliance to conditions of environment/CRZ NOC, Finishing to entrance lobby/s, plinth protection, paving of areas appurtenant to Building /Block/Tower, Compound Wall and all other requirements as may be required to obtain Occupation/Completion Certificate	100.00%

Table A (Block-L)

Sr. No.	Task/Activity	Percentage Work Done
1	Excavation	100.00%
2	1 number of Basement(s) and Plinth	100.00%

[Handwritten Signature]
PRAJIRA JAIN
ARCHITECT
(CA-2003-32690)
New Delhi

3	1 number of Podiums	100.00%
4	Stilt Floor	100.00%
5	16 number of Slabs of Super Structure	100.00%
6	Internal walls, Internal Plaster, Flooring within Flats/Premises, Doors and Windows in each of the Flats/Premises	100.00%
7	Sanitary Fittings within the Flat/Premises, Electrical Fittings within the Flat/premises	100.00%
8	Staircases, Lift Wells and Lobbies at each Floor level connecting Staircases and Lifts, Overhead and Underground Water Tanks	100.00%
9	The external plumbing and external plaster,Elevation, completion of terraces with waterproofing of the Building /Block/Tower	100.00%
10	Installation of lifts, water pumps, Fire Fighting Fittings and Equipments as per CFO NOC, Electrical fittings to Common Areas, electro-mechanical equipments, Compliance to conditions of environment/CRZ NOC, Finishing to entrance lobby/s, plinth protection, paving of areas appurtenant to Building /Block/Tower, Compound Wall and all other requirements as may be required to obtain Occupation/Completion Certificate	100.00%

Table A (Block-O)

Sr. No.	Task/Activity	Percentage Work Done
1	Excavation	100.00%
2	1 number of Basement(s) and Plinth	100.00%
3	1 number of Podiums	100.00%
4	Stilt Floor	100.00%
5	24 number of Slabs of Super Structure	100.00%
6	Internal walls, Internal Plaster, Flooring within Flats/Premises, Doors and Windows in each of the Flats/Premises	100.00%
7	Sanitary Fittings within the Flat/Premises, Electrical Fittings within the Flat/premises	100.00%
8	Staircases, Lift Wells and Lobbies at each Floor level connecting Staircases and Lifts, Overhead and Underground Water Tanks	100.00%
9	The external plumbing and external plaster,Elevation, completion of terraces with waterproofing of the Building /Block/Tower	100.00%
10	Installation of lifts, water pumps, Fire Fighting Fittings and Equipments as per CFO NOC, Electrical fittings to Common Areas, electro-mechanical equipments, Compliance to conditions of environment/CRZ NOC, Finishing to entrance lobby/s, plinth protection, paving of areas appurtenant to Building /Block/Tower, Compound Wall and all other requirements as may be required to obtain Occupation/Completion Certificate	100.00%


Table A (Block-Q)

Sr. No.	Task/Activity	Percentage Work Done
1	Excavation	100.00%
2	1 number of Basement(s) and Plinth	100.00%
3	1 number of Podiums	100.00%
4	Stilt Floor	100.00%
5	24 number of Slabs of Super Structure	100.00%
6	Internal walls, Internal Plaster, Flooring within Flats/Premises, Doors and Windows in each of the Flats/Premises	100.00%
7	Sanitary Fittings within the Flat/Premises, Electrical Fittings within the Flat/premises	100.00%
8	Staircases, Lift Wells and Lobbies at each Floor level connecting Staircases and Lifts, Overhead and Underground Water Tanks	100.00%
9	The external plumbing and external plaster,Elevation, completion of terraces with waterproofing of the Building /Block/Tower	100.00%
10	Installation of lifts, water pumps, Fire Fighting Fittings and Equipments as per CFO NOC, Electrical fittings to Common Areas, electro-mechanical equipments, Compliance to conditions of environment/CRZ NOC, Finishing to entrance lobby/s, plinth protection, paving of areas appurtenant to Building /Block/Tower, Compound Wall and all other requirements as may be required to obtain Occupation/Completion Certificate	100.00%

Table A (Block-R)

Sr. No.	Task/Activity	Percentage Work Done
1	Excavation	100.00%
2	1 number of Basement(s) and Plinth	100.00%
3	1 number of Podiums	100.00%
4	Stilt Floor	100.00%
5	24 number of Slabs of Super Structure	100.00%
6	Internal walls, Internal Plaster, Flooring within Flats/Premises, Doors and Windows in each of the Flats/Premises	100.00%
7	Sanitary Fittings within the Flat/Premises, Electrical Fittings within the Flat/premises	100.00%
8	Staircases, Lift Wells and Lobbies at each Floor level connecting Staircases and Lifts, Overhead and Underground Water Tanks	100.00%
9	The external plumbing and external plaster,Elevation, completion of terraces with waterproofing of the Building /Block/Tower	100.00%
10	Installation of lifts, water pumps, Fire Fighting Fittings and Equipments as per CFO NOC, Electrical fittings to Common Areas, electro-mechanical equipments, Compliance to conditions of environment/CRZ NOC, Finishing to entrance lobby/s, plinth protection, paving of areas appurtenant to Building /Block/Tower, Compound Wall and all other requirements as may be required to obtain Occupation/Completion Certificate	100.00%

Table A (Block-S)


PRATIKSHA JENA
ARCHITECT
(CA-2003-32690)
New Delhi

Sr. No.	Task/Activity	Percentage Work Done
1	Excavation	100.00%
2	1 number of Basement(s) and Plinth	100.00%
3	1 number of Podiums	100.00%
4	Stilt Floor	100.00%
5	24 number of Slabs of Super Structure	100.00%
6	Internal walls, Internal Plaster, Flooring within Flats/Premises, Doors and Windows in each of the Flats/Premises	100.00%
7	Sanitary Fittings within the Flat/Premises, Electrical Fittings within the Flat/premises	100.00%
8	Staircases, Lift Wells and Lobbies at each Floor level connecting Staircases and Lifts, Overhead and Underground Water Tanks	100.00%
9	The external plumbing and external plaster,Elevation, completion of terraces with waterproofing of the Building /Block/Tower	100.00%
10	Installation of lifts, water pumps, Fire Fighting Fittings and Equipments as per CFO NOC, Electrical fittings to Common Areas, electro-mechanical equipments, Compliance to conditions of environment/CRZ NOC, Finishing to entrance lobby/s, plinth protection, paving of areas appurtenant to Building /Block/Tower, Compound Wall and all other requirements as may be required to obtain Occupation/Completion Certificate	100.00%

Table A (Low Rise Floor- V1)

Sr. No.	Task/Activity	Percentage Work Done
1	Excavation	100.00%
2	1 number of Basement(s) and Plinth	100.00%
3	0 number of Podiums	N.A
4	4 number of Slabs of Super Structure	100.00%
5	Internal walls, Internal Plaster, Flooring within Flats/Premises, Doors and Windows in each of the Flats/Premises	100.00%
6	Sanitary Fittings within the Flat/Premises, Electrical Fittings within the Flat/premises	100.00%
7	Staircases, Lift Wells and Lobbies at each Floor level connecting Staircases and Lifts, Overhead and Underground Water Tanks	100.00%
8	The external plumbing and external plaster,Elevation, completion of terraces with waterproofing of the Building /Block/Tower	100.00%
9	Installation of lifts, water pumps, Fire Fighting Fittings and Equipments as per CFO NOC, Electrical fittings to Common Areas, electro-mechanical equipments, Compliance to conditions of environment/CRZ NOC, Finishing to entrance lobby/s, plinth protection, paving of areas appurtenant to Building /Block/Tower, Compound Wall and all other requirements as may be required to obtain Occupation/Completion Certificate	100.00%

Table A (Low Rise Floor- V2)

Sr. No.	Task/Activity	Percentage Work Done
1	Excavation	100.00%
2	1 number of Basement(s) and Plinth	100.00%
3	0 number of Podiums	N.A
4	4 number of Slabs of Super Structure	100.00%
5	Internal walls, Internal Plaster, Flooring within Flats/Premises, Doors and Windows in each of the Flats/Premises	100.00%
6	Sanitary Fittings within the Flat/Premises, Electrical Fittings within the Flat/premises	100.00%
7	Staircases, Lift Wells and Lobbies at each Floor level connecting Staircases and Lifts, Overhead and Underground Water Tanks	100.00%
8	The external plumbing and external plaster,Elevation, completion of terraces with waterproofing of the Building /Block/Tower	100.00%
9	Installation of lifts, water pumps, Fire Fighting Fittings and Equipments as per CFO NOC, Electrical fittings to Common Areas, electro-mechanical equipments, Compliance to conditions of environment/CRZ NOC, Finishing to entrance lobby/s, plinth protection, paving of areas appurtenant to Building /Block/Tower, Compound Wall and all other requirements as may be required to obtain Occupation/Completion Certificate	100.00%

Table A (Low Rise Floor- V3)

Sr. No.	Task/Activity	Percentage Work Done
1	Excavation	100.00%
2	1 number of Basement(s) and Plinth	100.00%
3	0 number of Podiums	N.A
4	4 number of Slabs of Super Structure	100.00%
5	Internal walls, Internal Plaster, Flooring within Flats/Premises, Doors and Windows in each of the Flats/Premises	100.00%
6	Sanitary Fittings within the Flat/Premises, Electrical Fittings within the Flat/premises	100.00%
7	Staircases, Lift Wells and Lobbies at each Floor level connecting Staircases and Lifts, Overhead and Underground Water Tanks	100.00%
8	The external plumbing and external plaster,Elevation, completion of terraces with waterproofing of the Building /Block/Tower	100.00%
9	Installation of lifts, water pumps, Fire Fighting Fittings and Equipments as per CFO NOC, Electrical fittings to Common Areas, electro-mechanical equipments, Compliance to conditions of environment/CRZ NOC, Finishing to entrance lobby/s, plinth protection, paving of areas appurtenant to Building /Block/Tower, Compound Wall and all other requirements as may be required to obtain Occupation/Completion Certificate	100.00%

Table A (Low Rise Floor- V4)

Sr. No.	Task/Activity	Percentage Work Done
---------	---------------	----------------------

PRABIRA JENA
ARCHITECT
(CA-2003-32690)
New Delhi

1	Excavation	100.00%
2	1 number of Basement(s) and Plinth	100.00%
3	0 number of Podiums	N.A
4	4 number of Slabs of Super Structure	100.00%
5	Internal walls, Internal Plaster, Flooring within Flats/Premises, Doors and Windows in each of the Flats/Premises	100.00%
6	Sanitary Fittings within the Flat/Premises, Electrical Fittings within the Flat/premises	100.00%
7	Staircases, Lift Wells and Lobbies at each Floor level connecting Staircases and Lifts, Overhead and Underground Water Tanks	100.00%
8	The external plumbing and external plaster,Elevation, completion of terraces with waterproofing of the Building /Block/Tower	100.00%
9	Installation of lifts, water pumps, Fire Fighting Fittings and Equipments as per CFO NOC, Electrical fittings to Common Areas, electro-mechanical equipments, Compliance to conditions of environment/CRZ NOC, Finishing to entrance lobby/s, plinth protection, paving of areas appurtenant to Building /Block/Tower, Compound Wall and all other requirements as may be required to obtain Occupation/Completion Certificate	100.00%

Table A (Low Rise Floor- V5)

Sr. No.	Task/Activity	Percentage Work Done
1	Excavation	100.00%
2	1 number of Basement(s) and Plinth	100.00%
3	0 number of Podiums	N.A
4	4 number of Slabs of Super Structure	100.00%
5	Internal walls, Internal Plaster, Flooring within Flats/Premises, Doors and Windows in each of the Flats/Premises	100.00%
6	Sanitary Fittings within the Flat/Premises, Electrical Fittings within the Flat/premises	100.00%
7	Staircases, Lift Wells and Lobbies at each Floor level connecting Staircases and Lifts, Overhead and Underground Water Tanks	100.00%
8	The external plumbing and external plaster,Elevation, completion of terraces with waterproofing of the Building /Block/Tower	100.00%
9	Installation of lifts, water pumps, Fire Fighting Fittings and Equipments as per CFO NOC, Electrical fittings to Common Areas, electro-mechanical equipments, Compliance to conditions of environment/CRZ NOC, Finishing to entrance lobby/s, plinth protection, paving of areas appurtenant to Building /Block/Tower, Compound Wall and all other requirements as may be required to obtain Occupation/Completion Certificate	100.00%

Table A (Low Rise Floor- V6)

Sr. No.	Task/Activity	Percentage Work Done
1	Excavation	100.00%
2	1 number of Basement(s) and Plinth	100.00%
3	0 number of Podiums	N.A
4	4 number of Slabs of Super Structure	100.00%
5	Internal walls, Internal Plaster, Flooring within Flats/Premises, Doors and Windows in each of the Flats/Premises	100.00%
6	Sanitary Fittings within the Flat/Premises, Electrical Fittings within the Flat/premises	100.00%
7	Staircases, Lift Wells and Lobbies at each Floor level connecting Staircases and Lifts, Overhead and Underground Water Tanks	100.00%
8	The external plumbing and external plaster,Elevation, completion of terraces with waterproofing of the Building /Block/Tower	100.00%
9	Installation of lifts, water pumps, Fire Fighting Fittings and Equipments as per CFO NOC, Electrical fittings to Common Areas, electro-mechanical equipments, Compliance to conditions of environment/CRZ NOC, Finishing to entrance lobby/s, plinth protection, paving of areas appurtenant to Building /Block/Tower, Compound Wall and all other requirements as may be required to obtain Occupation/Completion Certificate	100.00%

Table A (Low Rise Floor- V7)

Sr. No.	Task/Activity	Percentage Work Done
1	Excavation	100.00%
2	1 number of Basement(s) and Plinth	100.00%
3	0 number of Podiums	N.A
4	4 number of Slabs of Super Structure	100.00%
5	Internal walls, Internal Plaster, Flooring within Flats/Premises, Doors and Windows in each of the Flats/Premises	100.00%
6	Sanitary Fittings within the Flat/Premises, Electrical Fittings within the Flat/premises	95.00%
7	Staircases, Lift Wells and Lobbies at each Floor level connecting Staircases and Lifts, Overhead and Underground Water Tanks	95.00%
8	The external plumbing and external plaster,Elevation, completion of terraces with waterproofing of the Building /Block/Tower	90.00%
9	Installation of lifts, water pumps, Fire Fighting Fittings and Equipments as per CFO NOC, Electrical fittings to Common Areas, electro-mechanical equipments, Compliance to conditions of environment/CRZ NOC, Finishing to entrance lobby/s, plinth protection, paving of areas appurtenant to Building /Block/Tower, Compound Wall and all other requirements as may be required to obtain Occupation/Completion Certificate	90.00%

Table A (Low Rise Floor- V8)

Sr. No.	Task/Activity	Percentage Work Done
1	Excavation	100.00%
2	1 number of Basement(s) and Plinth	100.00%

[Signature]
PRABIR KUMAR
ARCHITECT
(CA-2003-32690)
New Delhi

3	0 number of Podiums	N.A
4	4 number of Slabs of Super Structure	100.00%
5	Internal walls, Internal Plaster, Flooring within Flats/Premises, Doors and Windows in each of the Flats/Premises	100.00%
6	Sanitary Fittings within the Flat/Premises, Electrical Fittings within the Flat/premises	90.00%
7	Staircases, Lift Wells and Lobbies at each Floor level connecting Staircases and Lifts, Overhead and Underground Water Tanks	95.00%
8	The external plumbing and external plaster,Elevation, completion of terraces with waterproofing of the Building /Block/Tower	90.00%
9	Installation of lifts, water pumps, Fire Fighting Fittings and Equipments as per CFO NOC, Electrical fittings to Common Areas, electro-mechanical equipments, Compliance to conditions of environment/CRZ NOC, Finishing to entrance lobby/s, plinth protection, paving of areas appurtenant to Building /Block/Tower, Compound Wall and all other requirements as may be required to obtain Occupation/Completion Certificate	90.00%

Table A (Low Rise Floor- V9)

Sr. No.	Task/Activity	Percentage Work Done
1	Excavation	100.00%
2	1 number of Basement(s) and Plinth	100.00%
3	0 number of Podiums	N.A
4	4 number of Slabs of Super Structure	100.00%
5	Internal walls, Internal Plaster, Flooring within Flats/Premises, Doors and Windows in each of the Flats/Premises	90.00%
6	Sanitary Fittings within the Flat/Premises, Electrical Fittings within the Flat/premises	85.00%
7	Staircases, Lift Wells and Lobbies at each Floor level connecting Staircases and Lifts, Overhead and Underground Water Tanks	90.00%
8	The external plumbing and external plaster,Elevation, completion of terraces with waterproofing of the Building /Block/Tower	60.00%
9	Installation of lifts, water pumps, Fire Fighting Fittings and Equipments as per CFO NOC, Electrical fittings to Common Areas, electro-mechanical equipments, Compliance to conditions of environment/CRZ NOC, Finishing to entrance lobby/s, plinth protection, paving of areas appurtenant to Building /Block/Tower, Compound Wall and all other requirements as may be required to obtain Occupation/Completion Certificate	80.00%

Table A (Low Rise Floor- V10)

Sr. No.	Task/Activity	Percentage Work Done
1	Excavation	100.00%
2	1 number of Basement(s) and Plinth	20.00%
3	0 number of Podiums	N.A
4	4 number of Slabs of Super Structure	25.00%
5	Internal walls, Internal Plaster, Flooring within Flats/Premises, Doors and Windows in each of the Flats/Premises	0.00%
6	Sanitary Fittings within the Flat/Premises, Electrical Fittings within the Flat/premises	0.00%
7	Staircases, Lift Wells and Lobbies at each Floor level connecting Staircases and Lifts, Overhead and Underground Water Tanks	0.00%
8	The external plumbing and external plaster,Elevation, completion of terraces with waterproofing of the Building /Block/Tower	0.00%
9	Installation of lifts, water pumps, Fire Fighting Fittings and Equipments as per CFO NOC, Electrical fittings to Common Areas, electro-mechanical equipments, Compliance to conditions of environment/CRZ NOC, Finishing to entrance lobby/s, plinth protection, paving of areas appurtenant to Building /Block/Tower, Compound Wall and all other requirements as may be required to obtain Occupation/Completion Certificate	0.00%

Table A (Low Rise Floor- V11)

Sr. No.	Task/Activity	Percentage Work Done
1	Excavation	100.00%
2	1 number of Basement(s) and Plinth	100.00%
3	0 number of Podiums	N.A
4	4 number of Slabs of Super Structure	0.00%
5	Internal walls, Internal Plaster, Flooring within Flats/Premises, Doors and Windows in each of the Flats/Premises	0.00%
6	Sanitary Fittings within the Flat/Premises, Electrical Fittings within the Flat/premises	0.00%
7	Staircases, Lift Wells and Lobbies at each Floor level connecting Staircases and Lifts, Overhead and Underground Water Tanks	0.00%
8	The external plumbing and external plaster,Elevation, completion of terraces with waterproofing of the Building /Block/Tower	0.00%
9	Installation of lifts, water pumps, Fire Fighting Fittings and Equipments as per CFO NOC, Electrical fittings to Common Areas, electro-mechanical equipments, Compliance to conditions of environment/CRZ NOC, Finishing to entrance lobby/s, plinth protection, paving of areas appurtenant to Building /Block/Tower, Compound Wall and all other requirements as may be required to obtain Occupation/Completion Certificate	0.00%

Table A (Low Rise Floor- V12)

Sr. No.	Task/Activity	Percentage Work Done
1	Excavation	100.00%
2	1 number of Basement(s) and Plinth	100.00%
3	0 number of Podiums	N.A
4	4 number of Slabs of Super Structure	0.00%


PRAHIRA SINGH
ARCHITECT
(CA-2003-32000)
New Delhi

5	Internal walls, Internal Plaster, Flooring within Flats/Premises, Doors and Windows in each of the Flats/Premises	0.00%
6	Sanitary Fittings within the Flat/Premises, Electrical Fittings within the Flat/premises	0.00%
7	Staircases, Lift Wells and Lobbies at each Floor level connecting Staircases and Lifts, Overhead and Underground Water Tanks	0.00%
8	The external plumbing and external plaster,Elevation, completion of terraces with waterproofing of the Building /Block/Tower	0.00%
9	Installation of lifts, water pumps, Fire Fighting Fittings and Equipments as per CFO NOC, Electrical fittings to Common Areas, electro-mechanical equipments, Compliance to conditions of environment/CRZ NOC, Finishing to entrance lobby/s, plinth protection, paving of areas appurtenant to Building /Block/Tower, Compound Wall and all other requirements as may be required to obtain Occupation/Completion Certificate	0.00%

Table A (Low Rise Floor- V14)

Sr. No.	Task/Activity	Percentage Work Done
1	Excavation	100.00%
2	1 number of Basement(s) and Plinth	100.00%
3	0 number of Podiums	N.A
4	4 number of Slabs of Super Structure	0.00%
5	Internal walls, Internal Plaster, Flooring within Flats/Premises, Doors and Windows in each of the Flats/Premises	0.00%
6	Sanitary Fittings within the Flat/Premises, Electrical Fittings within the Flat/premises	0.00%
7	Staircases, Lift Wells and Lobbies at each Floor level connecting Staircases and Lifts, Overhead and Underground Water Tanks	0.00%
8	The external plumbing and external plaster,Elevation, completion of terraces with waterproofing of the Building /Block/Tower	0.00%
9	Installation of lifts, water pumps, Fire Fighting Fittings and Equipments as per CFO NOC, Electrical fittings to Common Areas, electro-mechanical equipments, Compliance to conditions of environment/CRZ NOC, Finishing to	0.00%

Table A (Low Rise Floor- V15)

Sr. No.	Task/Activity	Percentage Work Done
1	Excavation	100.00%
2	1 number of Basement(s) and Plinth	100.00%
3	0 number of Podiums	N.A
4	4 number of Slabs of Super Structure	100.00%
5	Internal walls, Internal Plaster, Flooring within Flats/Premises, Doors and Windows in each of the Flats/Premises	100.00%
6	Sanitary Fittings within the Flat/Premises, Electrical Fittings within the Flat/premises	60.00%
7	Staircases, Lift Wells and Lobbies at each Floor level connecting Staircases and Lifts, Overhead and Underground Water Tanks	90.00%
8	The external plumbing and external plaster,Elevation, completion of terraces with waterproofing of the Building /Block/Tower	75.00%
9	Installation of lifts, water pumps, Fire Fighting Fittings and Equipments as per CFO NOC, Electrical fittings to Common Areas, electro-mechanical equipments, Compliance to conditions of environment/CRZ NOC, Finishing to entrance lobby/s, plinth protection, paving of areas appurtenant to Building /Block/Tower, Compound Wall and all other requirements as may be required to obtain Occupation/Completion Certificate	70.00%

Table A (Low Rise Floor- V16)

Sr. No.	Task/Activity	Percentage Work Done
1	Excavation	100.00%
2	1 number of Basement(s) and Plinth	100.00%
3	0 number of Podiums	N.A
4	4 number of Slabs of Super Structure	100.00%
5	Internal walls, Internal Plaster, Flooring within Flats/Premises, Doors and Windows in each of the Flats/Premises	80.00%
6	Sanitary Fittings within the Flat/Premises, Electrical Fittings within the Flat/premises	0.00%
7	Staircases, Lift Wells and Lobbies at each Floor level connecting Staircases and Lifts, Overhead and Underground Water Tanks	90.00%
8	The external plumbing and external plaster,Elevation, completion of terraces with waterproofing of the Building /Block/Tower	0.00%
9	Installation of lifts, water pumps, Fire Fighting Fittings and Equipments as per CFO NOC, Electrical fittings to Common Areas, electro-mechanical equipments, Compliance to conditions of environment/CRZ NOC, Finishing to entrance lobby/s, plinth protection, paving of areas appurtenant to Building /Block/Tower, Compound Wall and all other requirements as may be required to obtain Occupation/Completion Certificate	70.00%

Table A (Low Rise Floor- V17)

Sr. No.	Task/Activity	Percentage Work Done
1	Excavation	100.00%
2	1 number of Basement(s) and Plinth	100.00%
3	0 number of Podiums	N.A
4	4 number of Slabs of Super Structure	100.00%
5	Internal walls, Internal Plaster, Flooring within Flats/Premises, Doors and Windows in each of the Flats/Premises	85.00%
6	Sanitary Fittings within the Flat/Premises, Electrical Fittings within the Flat/premises	80.00%

PRADIRAJENA
ARCHITECT
(CA-2003-32690)
New Delhi

7	Staircases, Lift Wells and Lobbies at each Floor level connecting Staircases and Lifts, Overhead and Underground Water Tanks	90.00%
8	The external plumbing and external plaster,Elevation, completion of terraces with waterproofing of the Building /Block/Tower	80.00%
9	Installation of lifts, water pumps, Fire Fighting Fittings and Equipments as per CFO NOC, Electrical fittings to Common Areas, electro-mechanical equipments, Compliance to conditions of environment/CRZ NOC, Finishing to entrance lobby/s, plinth protection, paving of areas appurtenant to Building /Block/Tower, Compound Wall and all other requirements as may be required to obtain Occupation/Completion Certificate	70.00%

Table A (Low Rise Floor- V18)

Sr. No.	Task/Activity	Percentage Work Done
1	Excavation	100.00%
2	1 number of Basement(s) and Plinth	100.00%
3	0 number of Podiums	N.A
4	4 number of Slabs of Super Structure	100.00%
5	Internal walls, Internal Plaster, Flooring within Flats/Premises, Doors and Windows in each of the Flats/Premises	50.00%
6	Sanitary Fittings within the Flat/Premises, Electrical Fittings within the Flat/premises	20.00%
7	Staircases, Lift Wells and Lobbies at each Floor level connecting Staircases and Lifts, Overhead and Underground Water Tanks	0.00%
8	The external plumbing and external plaster,Elevation, completion of terraces with waterproofing of the Building /Block/Tower	0.00%
9	Installation of lifts, water pumps, Fire Fighting Fittings and Equipments as per CFO NOC, Electrical fittings to Common Areas, electro-mechanical equipments, Compliance to conditions of environment/CRZ NOC, Finishing to entrance lobby/s, plinth protection, paving of areas appurtenant to Building /Block/Tower, Compound Wall and all other requirements as may be required to obtain Occupation/Completion Certificate	0.00%

Table A (Low Rise Floor- V19)


Sr. No.	Task/Activity	Percentage Work Done
1	Excavation	100.00%
2	1 number of Basement(s) and Plinth	100.00%
3	0 number of Podiums	N.A
4	4 number of Slabs of Super Structure	100.00%
5	Internal walls, Internal Plaster, Flooring within Flats/Premises, Doors and Windows in each of the Flats/Premises	0.00%
6	Sanitary Fittings within the Flat/Premises, Electrical Fittings within the Flat/premises	0.00%
7	Staircases, Lift Wells and Lobbies at each Floor level connecting Staircases and Lifts, Overhead and Underground Water Tanks	0.00%
8	The external plumbing and external plaster,Elevation, completion of terraces with waterproofing of the Building /Block/Tower	0.00%
9	Installation of lifts, water pumps, Fire Fighting Fittings and Equipments as per CFO NOC, Electrical fittings to Common Areas, electro-mechanical equipments, Compliance to conditions of environment/CRZ NOC, Finishing to entrance lobby/s, plinth protection, paving of areas appurtenant to Building /Block/Tower, Compound Wall and all other requirements as may be required to obtain Occupation/Completion Certificate	0.00%

Table A (Low Rise Floor- V20)

Sr. No.	Task/Activity	Percentage Work Done
1	Excavation	100.00%
2	1 number of Basement(s) and Plinth	100.00%
3	0 number of Podiums	N.A
4	4 number of Slabs of Super Structure	100.00%
5	Internal walls, Internal Plaster, Flooring within Flats/Premises, Doors and Windows in each of the Flats/Premises	30.00%
6	Sanitary Fittings within the Flat/Premises, Electrical Fittings within the Flat/premises	0.00%
7	Staircases, Lift Wells and Lobbies at each Floor level connecting Staircases and Lifts, Overhead and Underground Water Tanks	0.00%
8	The external plumbing and external plaster,Elevation, completion of terraces with waterproofing of the Building /Block/Tower	0.00%
9	Installation of lifts, water pumps, Fire Fighting Fittings and Equipments as per CFO NOC, Electrical fittings to Common Areas, electro-mechanical equipments, Compliance to conditions of environment/CRZ NOC, Finishing to entrance lobby/s, plinth protection, paving of areas appurtenant to Building /Block/Tower, Compound Wall and all other requirements as may be required to obtain Occupation/Completion Certificate	0.00%

Table A (Low Rise Floor- V21)

Sr. No.	Task/Activity	Percentage Work Done
1	Excavation	100.00%
2	1 number of Basement(s) and Plinth	100.00%
3	0 number of Podiums	N.A
4	4 number of Slabs of Super Structure	75.00%
5	Internal walls, Internal Plaster, Flooring within Flats/Premises, Doors and Windows in each of the Flats/Premises	0.00%
6	Sanitary Fittings within the Flat/Premises, Electrical Fittings within the Flat/premises	0.00%
7	Staircases, Lift Wells and Lobbies at each Floor level connecting Staircases and Lifts, Overhead and Underground Water Tanks	0.00%
8	The external plumbing and external plaster,Elevation, completion of terraces with waterproofing of the Building /Block/Tower	0.00%



 PRABIR K. CHATTERJEE
 ARCHITECT
 (CA-2003-32690)
 New Delhi

9	Installation of lifts, water pumps, Fire Fighting Fittings and Equipments as per CFO NOC, Electrical fittings to Common Areas, electro-mechanical equipments, Compliance to conditions of environment/CRZ NOC, Finishing to entrance lobby/s, plinth protection, paving of areas appurtenant to Building /Block/Tower, Compound Wall and all other requirements as may be required to obtain Occupation/Completion Certificate	0.00%
---	--	-------

Table A (Low Rise Floor- V22)

Sr. No.	Task/Activity	Percentage Work Done
1	Excavation	100.00%
2	1 number of Basement(s) and Plinth	100.00%
3	0 number of Podiums	N.A
4	4 number of Slabs of Super Structure	100.00%
5	Internal walls, Internal Plaster, Flooring within Flats/Premises, Doors and Windows in each of the Flats/Premises	0.00%
6	Sanitary Fittings within the Flat/Premises, Electrical Fittings within the Flat/premises	0.00%
7	Staircases, Lift Wells and Lobbies at each Floor level connecting Staircases and Lifts, Overhead and Underground Water Tanks	0.00%
8	The external plumbing and external plaster,Elevation, completion of terraces with waterproofing of the Building /Block/Tower	0.00%
9	Installation of lifts, water pumps, Fire Fighting Fittings and Equipments as per CFO NOC, Electrical fittings to Common Areas, electro-mechanical equipments, Compliance to conditions of environment/CRZ NOC, Finishing to entrance lobby/s, plinth protection, paving of areas appurtenant to Building /Block/Tower, Compound Wall and all other requirements as may be required to obtain Occupation/Completion Certificate	0.00%


Table A (Low Rise Floor- V23)

Sr. No.	Task/Activity	Percentage Work Done
1	Excavation	100.00%
2	1 number of Basement(s) and Plinth	100.00%
3	0 number of Podiums	N.A
4	4 number of Slabs of Super Structure	100.00%
5	Internal walls, Internal Plaster, Flooring within Flats/Premises, Doors and Windows in each of the Flats/Premises	60.00%
6	Sanitary Fittings within the Flat/Premises, Electrical Fittings within the Flat/premises	20.00%
7	Staircases, Lift Wells and Lobbies at each Floor level connecting Staircases and Lifts, Overhead and Underground Water Tanks	0.00%
8	The external plumbing and external plaster,Elevation, completion of terraces with waterproofing of the Building /Block/Tower	0.00%
9	Installation of lifts, water pumps, Fire Fighting Fittings and Equipments as per CFO NOC, Electrical fittings to Common Areas, electro-mechanical equipments, Compliance to conditions of environment/CRZ NOC, Finishing to entrance lobby/s, plinth protection, paving of areas appurtenant to Building /Block/Tower, Compound Wall and all other requirements as may be required to obtain Occupation/Completion Certificate	0.00%

Table B

Internal & External Development Works in Respect of the Entire Registered Phase

S No	Common Areas and Facilities, Amenities	Proposed (Yes/No)	Details	Percentage of Work done
1	Internal Roads & Footpaths	Yes	Internal Roads & Footpaths works are in progress on site as per the site layout plan	85.00%
2	Water Supply	Yes	Water Supply works are in progress on site as per the site layout plan	85.00%
3	Sewarage (chamber, lines, Septic Tank, STP)	Yes	Sewarage (chamber, lines, Septic Tank, STP) work completed on site as per the site layout plan	100.00%
4	Strom Water Drains	Yes	Strom Water Drains works are in progress on site as per the site layout plan	90.00%
5	Landscaping & Tree Planting	Yes	Landscaping & Tree Planting works are in progress on site as per the site layout plan	80.00%
6	Street Lighting	Yes	Street Lighting works are in progress on site as per the site layout plan	90.00%
7	Community Buildings	Yes	Community Buildings works are in progress on site as per the site layout plan	30.00%
8	Treatment and disposal of sewage and sullage water	Yes	Treatment and disposal of sewage and sullage water work completed on the site as per the site layout plan	100.00%
9	Solid Waste management & Disposal	Yes	Treatment and disposal of sewage and sullage water work completed on the site as per the site layout plan	100.00%
10	Water conservation, Rain water harvesting	Yes	Water conservation, Rain water harvesting work completed on the site as per the site layout plan	100.00%
11	Energy management	Yes	Energy management work completed on the site as per the site layout plan	100.00%
12	Fire protection and fire safety requirements	Yes	Fire protection and fire safety requirements work are in progress on the site as per the site layout plan	100.00%
13	Electrical meter room, sub-station, receiving station	Yes	Fire protection and fire safety requirements work completed on the site as per the site layout plan	100.00%


PRAJIRA JENA
ARCHITECT
(CA-2003 32500)
New Delhi

14	Other (Option to Add more)	N.A	N.A
----	----------------------------	-----	-----

Yours Faithfully

PRABIRA JENA
ARCHITECT
(CA-2003-32690)
New Delhi

PRABIRA JENA

(License No. CA/2003/32690)

GAUR BIZ PARK, PLOT NO-01, ABHAY KHANNA II, INDIRAPURAM, GHAZIABAD (U.P)-201014