

ARCHITECT'S CERTIFICATE

AS ON 31/03/2021

No.....

Date: 31.03.2021

Subject: Certificate of Percentage of Completion of Construction Work of Rail Vihar at Village Manohar Pur Delhi Road IRWO Land At Moradabad. No. of Building(s)/71 DU's in Phase III Project [REGISTRATION NO UPRERA PRJ-8575] situated on the Khasra No/ Plot no (Khasra) 751 to 758 Demarcated by its boundaries (latitude and longitude of the end points)

- (A) 28° 49' 17" 78° 42' 33"
 (B) 28° 82' 05" 78° 71' 03"
 (C) 28° 82' 03" 78° 70' 86"
 (D) 28° 81' 97" 78° 70' 93"

Rail Vihar at Village Manohar Pur Delhi Road IRWO Moradabad Tehsil MORADABAD Competent/ Development authority MDA District Moradabad PIN 244001 admeasuring 19200 sq.mts. area being developed by INDIAN RAILWAY WELFARE ORGANISATION.

We M/s Rajesh Bhatnagar have undertaken assignment as Architect/Licensed Surveyor of certifying Percentage of Completion Work of the Rail Vihar at Village Manohar Pur Delhi Road IRWO Building(s)/71 DU's Block/ Tower (s) of Phase III Project, situated on the Khasra No/ Plot no 751 to 758 of village Manohar Delhi Road Moradabad Tehsil Moradabad competent/ development authority MDA District Moradabad PIN 244001 admeasuring 19200 sq.mts. area being developed by INDIAN RAILWAY WELFARE ORGANISATION.

1. Following technical professionals are appointed by owner / Promotor :-

- (i) M/s Rajesh Bhatnagar _____ as L.S. / Architect ;
 (ii) Shri Paresh Johary _____ as Structural Consultant
 (iii) M/s Rajesh Bhatnagar _____ as MEP Consultant
 (iv) Shri P.K Gupta, PM _____ as Site Supervisor

Based on Site Inspection, with respect to each of the Buildings /Blocks/Towers of the aforesaid Real Estate Project, I certify that as on the date of this certificate, the Percentage of Work done for each of the Buildings /Blocks/Towers of the Real Estate Project as registered vide number UPRERA PRJ-8575 under UPRERA is as per table A herein below. The percentage of the work executed with respect to each of the activity of the entire phase is detailed in the Table B.

Table A

Sr. No.	Task/Activity	Percentage of Work done
1	Excavation	42
2	Zero number of Basement(s) and Plinth	42
3	Zero number of Podiums	NIL
4	Stilt Floor	NIL
5	16 DU's of Slabs of Super Structure	32
6	Internal walls, Internal Plaster, Flooring within Flats/Premises, Doors and Windows in each of the Flats/Premises	14
7	Sanitary Fittings within the Flat/Premises, Electrical Fittings within the Flat/premises	10
8	Staircases, Lift Wells and Lobbies at each Floor level connecting Staircases and Lifts, Overhead and Underground Water Tanks	20
9	The external plumbing and external plaster,Elevation, completion of terraces with waterproofing of the Building /Block/Tower	23
10	Installation of lifts, water pumps, Fire Fighting Fittings and Equipments as per CFO NOC, Electrical fittings to Common Areas, electro-mechanical equipments, Compliance to conditions of environment/CRZ NOC, Finishing to entrance lobby/s, plinth protection, paving of areas appurtenant to Building /Block/Tower, Compound Wall and all other requirements as may be required to obtain Occupation/Completion Certificate	3

Table B**Internal & External Development Works in Respect of the Entire Registered Phase**

S No	Common Areas and Facilities, Amenities	Proposed (Yes/No)	Details	Percentage of Work done
1	Internal Roads & Footpaths	Yes	Filling of earth and WBM complete	40
2	Water Supply	Yes	Laying of pipe line	90
3	Sewerage (chamber, lines, Septic Tank, STP)	Yes	Laying of pipe line and manhole & STP	90
4	Storm Water Drains	Yes		NIL
5	Landscaping & Tree Planting	Yes	Grassing In Park	40
6	Street Lighting	Yes		NIL
7	Community Buildings	Yes	Ground Floor, First Floor and Second Floor Structure Complete	60
8	Treatment and disposal of sewage and sullage water	Yes	Sewrage storage tank complete	90
9	Solid Waste management & Disposal	No		NIL
10	Water conservation, Rain water harvesting	Yes	Rain water harvesting complete	100
11	Energy management	Yes	Solar Light and LED Street Lights	NIL
12	Fire protection and fire safety requirements	No		NIL
13	Electrical meter room, sub-station, receiving station	Yes	All Rooms Are Finished	80
14	Boundry Wall	Yes	Super structure with plaster and railing.	98
15	Other (Option to Add more) Retaining wall	No		NIL

Yours Faithfully


Signature & Name (IN BLOCK LETTERS) OF L.S./Architect
(License NO.....)

K. S. BHATNAGAR
 ARCHITECT
 MADABAD
 COA No. CA/83/7332