

NIRMAN CONSULTANTS

Architect

Sanjeev Kumar Singh

B.Arch, F.I.V.

Arch. Reg. No. - CA / 94/17950

Institution of Valuer Reg. No. - F-15108

FORM-REG 1

ARCHITECT'S CERTIFICATE

Subject: Certificate of Percentage of Completion of Construction Work of **Pocket B Sector J, SGC No. of Building(s)/ Block(s) of the Mother City Phase of the Project UPRERA PU9645** situated on the Khasra No/ Plot no **7, 8, 9, 11, 18, 19, 20, 39, 40, 41, 42, 43, 44 & 4**.
Demarcated by its boundaries **26.778362** to the North, **26.773298** to the South, **81.033029** to the East, **81.031886** to the West of village **Tehsil Sarojini Nagar**. Competent/ Development authority **Lucknow Development Authority**, District **Lucknow**, PIN **226002** admeasuring **68000** sq.mts. area being developed by **Ansal Properties & Infrastructure Limited**.
I/We **Sanjeev Kumar Singh** have undertaken assignment as Project Engineer for certifying Percentage of Completion Work of the **Pocket B Sector J, SGC Building(s)/Block/ Tower (s) of Mother City Phase of the Project**, situated on the Khasra No/ Plot no **7, 8, 9, 11, 18, 19, 20, 39, 40, 41, 42, 43, 44 & 4** of village **Tehsil Sarojini Nagar** competent/ development authority **Lucknow Development Authority**, District **Lucknow**, PIN **226002** admeasuring **68000** sq.mts. area being developed by **Ansal Properties & Infrastructure Limited**.

1. Following technical professionals are appointed by owner/promoter:

- (i) M/s/Shri/Smt. _____ as Architect
- (ii) M/s/Shri/Smt. _____ as Structural Consultant
- (iii) M/s/Shri/Smt. _____ as MEP Consultant
- (iv) M/s/Shri/Smt. _____ as Site Supervisor

Based on Site Inspection, with respect to each of the Buildings /Blocks/Towers of the aforesaid Real Estate Project, I certify that as on the date of this certificate, the Percentage of Work done for each of the Buildings /Blocks/Towers of the Real Estate Project as registered vide number _____ under UPRERA is as per table A herein below. The percentage of the work executed with respect to each of the activity of the entire phase is detailed in the Table B.

Sr. No.	Task/Activity	Percentage Work Done
1	Excavation	0%
2	number of Basement(s) and Plinth	0%
3	number of Podiums	0%
4	Stilt Floor	0%
5	number of Slabs of Super Structure	0%
6	Internal walls, Internal Plaster, Flooring within Flats/Premises, Doors and Windows in each of the	0%
7	Sanitary Fittings within the Flat/Premises, Electrical Fittings within the Flat/premises	0%
8	Staircases, Lift Wells and Lobbies at each Floor level connecting Staircases and Lifts, Overhead and	0%
9	The external plumbing and external plaster, Elevation, completion of terraces with waterproofing of the	0%
10	Installation of lifts, water pumps, Fire Fighting Fittings and Equipments as per CFO NOC, Electrical fittings to Common Areas, electro-mechanical equipments, Compliance to conditions of environment/CRZ NOC, Finishing to entrance lobby/s, plinth protection, paving of areas appurtenant to Building /Block/Tower, Compound Wall and all other requirements as may be required to obtain Occupation/Completion	0%

Table B
Internal & External Development Works in Respect of the Entire Registered Phase

S No	Common Areas and Facilities, Amenities	Proposed (Yes/No)	Details	Percentage of Work done
1	Internal Roads & Footpaths	Yes	Bitumen Road/CC/Pavers	0%
2	Water Supply	Yes	Deep Bore-well water supplied through Overhead Tank	0%
3	Sewerage (chambers, manholes, septic tanks, etc.)	Yes	NP2 Concrete House Pipe Network	0%
4	Storm Water Drains	Yes	NP2 Concrete House Pipe Network	0%
5	Landscaping & Tree Planting	Yes	Combination of Indigenous and Ornamental Plants	0%
6	Street Lighting	Yes	Illumination on Internal Roads	70%
7	Community Buildings	NO	N/A	0%
8	Treatment and disposal of sewage and sullage water	Yes	Connected to STP	60%
9	Solid Waste management & Disposal	Yes	House to House Connection	60%
10	Water conservation, Rain water harvesting	Yes	Ground Water Recharge System	0%
11	Energy management	Yes	As per Prevailing Laws	0%
12	Fire protection and fire safety requirements	Yes	As per NBC Norms	0%
13	Electrical meter room, sub-station, receiving station	Yes	Connected to Township Sub Station, Metered Supply to each & Every Units from Feeder Pylers	25%
14	Other (Option to Add more)	Yes	Parks, Benches, Pathways	0%

Yours Faithfully

ARCHITECT
SANJEEV KUMAR SINGH
C.O.A. REG.No.-CA/94/17950

Signature & Name (IN BLOCK LETTERS) OF
(License NO.)